

Provided By



**Home Inspections For A Better Peace Of Mind.**

Factory 8 3-11 Bate Close , Pakenham, Victoria, 3810, Australia  
P 0400886170  
inspections@abpom.com.au  
www.abpom.com.au

---

**Inspection Address**

**123 Homebuyer Road, Homebuyers Town, Victoria, 3000**



## Report Information

### Client Information

Client Name                      Mr & Mrs Homebuyer  
 Report Ordered By              Client

### Inspection Information

Report/Agreement #              Combined Building & Timber Pest Inspection Report  
 Inspection Date:                  02 Jan 2023  
 Inspection Time:                  07:00

### Pest And Building Inspection

#### **The Scope of the Inspection:**

This report Complies with Australian Building Standards AS 4349.1-2007. Inspection of Buildings Part 1: Pre-Purchase Inspections-Residential Buildings- Appendix "C" and with AS 4349.3-2010 (Visual Timber Pest Inspection Report)

Only the purchaser name at the front page of the report "Client" should rely on this report. If this report has been issued to you by a third party. You are not to rely on its findings or contents and seek to obtain your own independent pre purchase inspection report as this report or its contents is non transferable.

The inspection WILL NOT report on items listed in Appendix "D" of AS43491.2007

If the property is part of a Strata or Company Title , then Appendix "B" of the Australian Standards applies.

#### **Special Requirements:**

Unless stated otherwise in the report It is acknowledged that there are no special requirements placed on this inspection that are outside the scope of the abovementioned Australian Standard.

#### **Changes to the Pre Inspection Agreement:**

Unless stated otherwise in the report It is acknowledged that if any inspection agreement is in place in respect to this inspection, no changes have been made between the scope of the pre-Inspection Agreement and the scope of this inspection report.

**Please read the entire report.** Refer to the terms & conditions as they form part of the report

### Areas to be Inspected and Restrictions

The Building and the site including fencing that is up to 30 meters from the building and within the boundaries of the site. Where present and accessible, the Inspection shall include.

(a) The interior of the building.

- (b) The roof space.
- (c) The exterior of the building
- (d) The sub-floor space
- (e) The roof exterior
- (f) The property within 30 m of the building subject to inspection.

### **Visual Inspection Only**

This is a visual inspection only limited to those areas and sections of the property fully accessible and visible to the inspector on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/ sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, behind stored goods in cupboards and other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. Visible timbers cannot be destructively probed or hit without the written permission of the property owner.

### **Very Important note to the purchaser.**

In the event that areas where access is restricted or not accessed structural defects, termite damage or activity may be present but not seen. Access should be provided and a follow up or re-Inspection should take place. This Inspection will be provided for you at a fee. Please consult with the vendor and request full access to restricted areas. This should be done prior to a decision to purchase.

## Table of Contents

- 1. PROPERTY AND INSPECTION INFORMATION**
- 2. SITE**
- 3. ROOF AND GUTTER**
- 4. HOT WATER SYSTEM**
- 5. EXTERIOR**
- 6. GARAGE - CARPORT**
- 7. STAIRS- PERGOLA- BALCONIES-DECKS**
- 8. INTERIORS**
- 9. BATHROOM(S)**
- 10. KITCHEN & LAUNDRY**
- 11. ROOF VOID**
- 12. SUBFLOOR**
- 13. CONCLUSION**
- 14. ACCESS AND RESTRICTIONS**
- 15. TIMBER PEST FINDINGS**
- 16. CONDUCTIVE CONDITIONS**
- 17. OVERALL ASSESSMENT**

## Summary Of Major Defects And Safety Hazards

**Below Is A Summary Of Significant Items Requiring Immediate Action.**

Section	Location	Name	Comment
SITE	Driveway	Driveway Condition	Driveway has visible tripping hazards. Repairs are required by a qualified concreter to avoid potential injury. Considered a Safety hazard
SITE	Driveway	Driveway Condition	The driveway is in poor condition replacement recommended. Contact a licensed concreter for a quotation.
SITE	Paths	Pathways Condition	The concrete path is in poor condition replacement recommended.
SITE	Paths	Pathways Condition	Driveway has visible tripping hazards on paths/driveway- this may not have any affect on the structural integrity of the actual dwelling, however, repairs are required by a qualified concreter to avoid potential injury. Considered a safety hazard.
SITE	Fences & Gates	Overall Condition	Fungal decay is visible have a fence contractor to replace decaying fence.
SITE	Surface Drainage	Drainage Findings	There is evidence around the home paths that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.
SITE	Surface Drainage	Drains	Gutter join is leaking seek expert advice from a licensed plumber for repair.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Valley gutter mortar cracking and openings visible - Recommendations: A qualified roof restoration contractor should be engaged for advice and recommendations.
EXTERIOR	Weep Holes and Ventilation	Findings	Ventilation is poor seek expert advice from a licensed builder and damp specialist for improving subfloor ventilation.
EXTERIOR	Exterior Walls	Condition	Cracks noted. Possible causes may be foundation movement. Support structure deflection. Thermal movement and moisture uptake or loss, failure under external loads. In in the inspectors opinion these cracks require further assessment. A structural engineer should be consulted for further evaluation and advice. Significant lose Major defect.
EXTERIOR	Exterior Walls	Condition	Rising damp detected. A qualified damp proof specialist should be engaged for advice and recommendations. Accurate diagnosis of the cause and extent of the damp problem is very important. Note: It is imperative that specialist advice be sought to obtain accurate diagnosis of the cause and extent of the damp problem and it is advised that you have assessed prior to purchasing the dwelling as can be quite costly if a damp proof course has to be reinstated. Significant lose Major defect.

EXTERIOR	Exterior Walls	Condition	Salt residue on rear sliding door brickwork at ground level - Salt residue is caused by poor drainage to paved area as pavers are undulating and cause ponding and surface water to this area. Recommend seeking expert advice from a licensed builder, plumber, or skilful handyman to level out pavers and install more draining points.
EXTERIOR	Rising Damp	Rising Damp Findings	High moisture readings were to the exterior walls. We recommend specialist in this field be engaged for further evaluation and repairs.
EXTERIOR	Rising Damp	Rising Damp Findings	Salt residue & brick mortar deterioration on lower wall visible - Further investigation required. Recommendations: A specialist in this field should be engaged for advice and recommendations.
EXTERIOR	Rising Damp	Rising Damp Findings	Salt residue on lower external wall visible - Salt residue can be associated with rising damp problems. Recommendations: Further investigation by a specialist in this field is recommended
EXTERIOR	Rising Damp	Damp Proof Course	A lead damp proof coursing material is visible. Lead damp proof coursing is known to break down with age when in contact with certain minerals which may be present in the brickwork or drawn up from the foundation soil. Rising damp may become a problem and the damp proof coursing material may need to be replaced.
EXTERIOR	Porch Area	Ceiling Lining Condition	Roof tiles are in poor condition require immediate replacement. Seek expert advice from a roof tiler.
STAIRS- PERGOLA- BALCONIES- DECKS	Stairs & Steps	Treads	Tripping Hazard recommend rectifying to prevent harm or injury.
INTERIORS	Lounge Room	Flooring	Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
INTERIORS	Dining Room	Flooring	Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
INTERIORS	Bedroom 3	Flooring	Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
BATHROOM(S)	Toilet Inside	Walls	Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.
BATHROOM(S)	Toilet Inside	Flooring	Borer damage to floor linings - Some weakened boards may require assessment/replacement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
BATHROOM(S)	Bathroom 1	Ceiling	Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

BATHROOM(S)	Bathroom 1	Walls	Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.
BATHROOM(S)	Bathroom 1	Flooring	Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Ceiling sagging - Requires repair from a safety perspective - Recommendations: I recommend you contact a licensed plasterer for further advice and recommendations.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Floor	Borer damage to floor linings - Some weakened boards may require assessment/replacement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Floor	Unevenness visible in floor - Floor linings may require removal to ascertain cause. Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Sink and Taps	General ageing & deterioration of the sink, cupboards and benches. Recommendations: Update kitchen.
KITCHEN & LAUNDRY	Laundry Findings	Walls	Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.
KITCHEN & LAUNDRY	Laundry Findings	Flooring	Unevenness visible in floor - Floor linings may require removal to ascertain cause. Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.
ROOF VOID	Roof Void Findings	Roof Cladding	Efflorescence observed indicating water absorption. White stains on tile roofs are typically an efflorescence deposit and may indicate that the tile is absorbing water, thus nearing end of life. A qualified roof restorer/tiler should be engaged for advice and recommendations. Roof tiles are in extremely poor condition and require immediate replacement.
SUBFLOOR	Sub-Floor Observation.	Piers And Foundation Walls	Timber fungal decay evident in stumps. Recommendations: A qualified re-stumping contractor should be engaged for advice and recommendations. Major defect significant lose.
SUBFLOOR	Sub-Floor Observation.	Ventilation	Inadequate ventilation observed. Additional vents or mechanical ventilation required. This may be conducive to timber decay and other damp related issues. Improvement to the ventilation is recommended. Contact a licensed builder for advise and rectification.
CONCLUSION	Condition Of Inspected Structure	The incidence of Major Defects	The incidence of major defects in this residential building as compared with similar buildings is considered HIGH

TIMBER PEST FINDINGS	3.6 Borer Findings	Was Visible Evidence of Borer Found	Yes, lyctus brunneus was found- commonly known as the powder post beetle. Large Timber pest infestation visible seek expert advice from a licensed builder for non-susceptible Timbers. Major defect.
CONDUCTIVE CONDITIONS	4. Conducive Conditions to Timber Pests	Water leaks	Downpipe Base is broken seek immediate advice from a licensed plumber for immediate repair.
CONDUCTIVE CONDITIONS	4.1 Hot Water Unit Overflow	Was the overflow sufficiently drained	No - Divert hot water overflow away from the building perimeter
CONDUCTIVE CONDITIONS	4.1 Hot Water Unit Overflow	Was the Air Conditioner Sufficiently Drained	No - Divert A/C overflow away from the building perimeter
CONDUCTIVE CONDITIONS	6. Areas Found Conducive To Termite Infestation	Conducive Areas Requiring Amendments	Rising damp detected. A qualified damp proof specialist should be engaged for advice and recommendations. Accurate diagnosis of the cause and extent of the damp problem is very important. Note: It is imperative that specialist advice be sought to obtain accurate diagnosis of the cause and extent of the damp problem and it is advised that you have assessed prior to purchasing the dwelling as can be quite costly if a damp proof course has to be reinstated.
CONDUCTIVE CONDITIONS	6. Areas Found Conducive To Termite Infestation	Conducive Areas Requiring Amendments	Downpipe Base is cracked seek expert advice from a licensed plumber for immediate repair.
CONDUCTIVE CONDITIONS	6. Areas Found Conducive To Termite Infestation	Conducive Areas Requiring Amendments	Downpipe Base is broken seek immediate advice from a licensed plumber for immediate repair.
CONDUCTIVE CONDITIONS	6. Areas Found Conducive To Termite Infestation	Conducive Areas Requiring Amendments	Downpipe is rusted seek expert advice from a licensed plumber to repair immediately.
OVERALL ASSESSMENT	10. Subterranean Termite Treatment Recommendation	Treatment Recommendation	Termite prevention wasn't detected during inspection treatment is due now.



## Summary Of Minor Defects

**Below Is A Summary Of Defects Other Than Major Defects.**

Section	Location	Name	Comment
SITE	Driveway	Driveway Condition	Surface raised and settled in some areas. This can cause water ponding. Relaying recommended.
SITE	Driveway	Driveway Condition	There is evidence around the Driveway that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.
SITE	Paths	Pathways Condition	Surface raised and settled in some areas. This can cause water ponding. Relaying recommended.
SITE	Paths	Pathways Condition	There is evidence around the home paths that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.
SITE	Fences & Gates	Overall Condition	Damage was noted to the timber fence. Contact a fencing contractor for repairs.
SITE	Fences & Gates	Overall Condition	Damage to gates noted. contact a licensed fencing contractor for repairs
SITE	Fences & Gates	Overall Condition	The gate does not latch. Have repaired by a licensed fencer.
SITE	Fences & Gates	Overall Condition	Fence is leaning seek advice from a fence contractor.
SITE	Surface Drainage	Drains	Debris evident in/around drains - Requires cleaning out.
SITE	Shed	Shed Condition	The shed is considered in poor condition and repairs/ replacement should be considered. A replacement shed should be considered.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Deterioration & ageing evident. I recommend you contact a roof restorer to clean, seal, and repoint the mortar.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Mortar cracks visible. We recommend having these repaired by a licensed roofer as they contribute to water ingress. Whilst common on properties of this age we recommend repair it may result in water ingress into the roof cavity
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Tile lift/unevenness visible - Recommendations: Have roofer re-fix. Considered a minor defect but has the potential to become a Major defect if repairs aren't carried out immediately due to water ingress into the roof cavity
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Moss has built up on the tiles over time. It is preferable to have removed / cleaned to prevent deterioration. Recommendations: A qualified roof restoration contractor should be engaged for advice and recommendations.

ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Trees overhang on roof - Recommendations: Cut back to prevent damage and blocked guttering and associated problems.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Roof line unevenness visible - Recommendations: May be related to some gaining or loosening of the burrup truss. See a carpenter for advice and recommendations. Considered a Minor Defect, however has the potential to be a costly repair.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Roof valley has visible rust seek expert advice from a licensed roof plumber.
ROOF AND GUTTER	Roof Covering	Roof Clad Condition	Broken Roof Tiles seek expert advice from a roof tiler.
ROOF AND GUTTER	Roof Covering	Flashing Conditions	Minor flashing rust sections - Recommendations: A qualified roofer should be engaged for repairs and recommendations.
ROOF AND GUTTER	Guttering	Gutter Findings	Debris in guttering areas- this requires cleaning out to prevent blocking of down pipes and leaking into eaves and fascia. Recommendations: Have gutters cleaned and assessed by a plumber for adequate fall. Also regularly clean to prevent ponding. Ponding water will contribute to rust.
ROOF AND GUTTER	Guttering	Gutter Findings	There is evidence of leaking gutters. Contact a roof plumber for advice and repairs.
ROOF AND GUTTER	Down Pipes	Down Pipe Findings	Impact damage noted to down pipe. Contact a roof plumber for replacement as required.
ROOF AND GUTTER	Down Pipes	Down Pipe Findings	Repair to downpipe is visible seek expert advice from a licensed plumber.
HOT WATER SYSTEM	Hot Water Unit	Hot Water Unit Findings	On visual inspection the hot water suit appears dilapidated. Anticipate a replacement in the not too distant future.
EXTERIOR	External Door Components	Door Findings	General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
EXTERIOR	External Door Components	Door Findings	Rust in door/door frame - Recommendations: General repairs required.
EXTERIOR	External Door Components	Door Findings	Security flyscreen damage- recommendations: A qualified carpenter should be engaged for advice and recommendations.
EXTERIOR	Exterior Walls	Condition	Mortar erosion between the brickwork is eroded. Contact a licensed bricklayer for repairs.
EXTERIOR	Exterior Walls	Condition	Moisture readings to lower coarse row of bricks recommended to seek expert advice from a damp course specialist to help reduce moisture.
EXTERIOR	Exterior Windows	Overall Condition	Gaps between window frame and wall cladding evident - This can be due to poor workmanship, wall movement, footings settlement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
EXTERIOR	Exterior Windows	Overall Condition	Lintel rust in sections. This may cause cracking in wall linings above the window - Recommendations: A qualified brick layer should be engaged for repairs and recommendations.

EXTERIOR	Eaves	Eave Condition	Minor eave deterioration & ageing evident. Recommendations: Maintenance works, general upkeep should be carried out.
EXTERIOR	Eaves	Eave Condition	Eave lining damage visible. Recommendations: A qualified carpenter should be engaged for repairs.
EXTERIOR	Eaves	Eave Condition	We strongly recommend you re-finish and paint the eaves and timber trim to preserve same.
EXTERIOR	Eaves	Eave Condition	Possible Asbestos seek expert advice from a a Asbestos company.
EXTERIOR	Fascia and Barge Boards	Condition	Minor deterioration & ageing evident. Recommendations: Maintenance works, general upkeep should be carried out.
EXTERIOR	Fascia and Barge Boards	Condition	Paint / finish was deteriorated in areas and is in need of maintenance - Sanding back affected areas and painting required.
EXTERIOR	Fascia and Barge Boards	Condition	Timber fungal decay (rot) visible. Recommendations: A qualified carpenter should be engaged to replace all affected timbers.
EXTERIOR	Fascia and Barge Boards	Condition	Separated on corner. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
GARAGE - CARPORT	Garaging	Roof And Gutter	Gutter rust/penetrations - The guttering has excessive rust where leaking will occur. Recommendations: The gutters require replacement by a roof plumber to prevent further deterioration of cladding. Considered a Minor Defect
GARAGE - CARPORT	Garaging	Roof And Gutter	Debris visible have guttering cleaned every 6 months to prevent moisture issues.
GARAGE - CARPORT	Garaging	Wall Cladding Findings	Physical wall damage visible - Recommendations: Engage a licensed builder to assess/repair.
GARAGE - CARPORT	Garaging	Wall Cladding Findings	Rust is visible seek expert advice from a licensed shed specialist.
GARAGE - CARPORT	Garaging	Door Findings	General age deterioration of the garage door/components. Recommendations: General repairs/maintenance as required.
GARAGE - CARPORT	Garaging	Door Findings	Impact damage observed. Repairs/Replacement recommended.
GARAGE - CARPORT	Garaging	Internal Wall Findings	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
GARAGE - CARPORT	Garaging	Floor Findings	Minor hairline slab cracks - Note. Whilst these cracks appeared to be minor at the time of inspection, we strongly recommend you monitor these cracks and if worsening occurs contact a qualified concreter for further advice.
STAIRS-PERGOLA-BALCONIES-DECKS	Verandah Findings	Veranda Floor Frame	Cracked Concrete considered minor defect recommend to seek advice from Concreter.

STAIRS- PERGOLA- BALCONIES- DECKS	Verandah Findings	Veranda Posts	Paint Deterioration seek expert advice from painter
INTERIORS	Doors	Front Entry Doors	Entry door / frame deterioration - General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
INTERIORS	Doors	Other Doors	Uneven / out of square entry door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
INTERIORS	Doors	Other Doors	Doors have impact Damage recommendations are to replace doors.
INTERIORS	Doors	Other Doors	Door deterioration - General age has occurred to door and components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
INTERIORS	Entrance	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Entrance	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Entrance	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Entrance	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Entrance	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
INTERIORS	Hallways	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Hallways	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Hallways	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Hallways	Walls	Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however we recommend monitor these cracks and if become wider or longer, you will need to contact a structural engineers to assess.
INTERIORS	Hallways	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Hallways	Walls	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

INTERIORS	Hallways	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.
INTERIORS	Hallways	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
INTERIORS	Lounge Room	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Lounge Room	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Lounge Room	Ceiling	Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.
INTERIORS	Lounge Room	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Lounge Room	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Lounge Room	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Lounge Room	Walls	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Lounge Room	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.
INTERIORS	Lounge Room	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
INTERIORS	Dining Room	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Dining Room	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Dining Room	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Dining Room	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.
INTERIORS	Dining Room	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
INTERIORS	Bedroom 1	Ceiling	Settlement Cracks Noted . These are typical and generally patch and paint will suffice, however Monitoring these cracks advised for 12 months and if become wider or longer, you will need to contact a structural engineers to assess.
INTERIORS	Bedroom 1	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

INTERIORS	Bedroom 1	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Bedroom 1	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Bedroom 1	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Bedroom 1	Flooring	General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.
INTERIORS	Bedroom 1	Flooring	Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.
INTERIORS	Bedroom 2	Door	Impact damage observed. Repairs / Replacement recommended
INTERIORS	Bedroom 2	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Bedroom 2	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Bedroom 2	Ceiling	Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.
INTERIORS	Bedroom 2	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Bedroom 2	Ceiling	Ceiling stains - No moisture readings obtained. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. All water damaged plaster replaced by a qualified plasterer.
INTERIORS	Bedroom 2	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Bedroom 2	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Bedroom 2	Walls	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Bedroom 2	Flooring	General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.
INTERIORS	Bedroom 2	Flooring	Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.
INTERIORS	Bedroom 2	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

INTERIORS	Bedroom 3	Door	Uneven / out of square door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
INTERIORS	Bedroom 3	Door	Impact damage observed. Repairs / Replacement recommended
INTERIORS	Bedroom 3	Ceiling	General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Bedroom 3	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Bedroom 3	Ceiling	Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.
INTERIORS	Bedroom 3	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
INTERIORS	Bedroom 3	Ceiling	Ceiling stains - No moisture readings obtained. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. All water damaged plaster replaced by a qualified plasterer.
INTERIORS	Bedroom 3	Walls	General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
INTERIORS	Bedroom 3	Walls	Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however we recommend monitor these cracks and if become wider or longer, you will need to contact a structural engineers to assess.
INTERIORS	Bedroom 3	Walls	Impact damage noted. Contact a licensed plasterer for repairs.
INTERIORS	Bedroom 3	Walls	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
INTERIORS	Bedroom 3	Flooring	General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.
INTERIORS	Bedroom 3	Flooring	Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.
INTERIORS	Bedroom 3	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.
BATHROOM(S)	Toilet Inside	Ceiling	Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however monitoring these cracks advised for 12 months and if become wider or longer, you will need to contact a structural engineers to assess.
BATHROOM(S)	Toilet Inside	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.

BATHROOM(S)	Toilet Inside	Walls	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
BATHROOM(S)	Toilet Inside	Walls	Wall paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
BATHROOM(S)	Toilet Inside	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
BATHROOM(S)	Bathroom 1	Door	Uneven / out of square door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
BATHROOM(S)	Bathroom 1	Ceiling	General ageing and/or denting and/or wear and/or previous patching and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
BATHROOM(S)	Bathroom 1	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
BATHROOM(S)	Bathroom 1	Ceiling	Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
BATHROOM(S)	Bathroom 1	Walls	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
BATHROOM(S)	Bathroom 1	Walls	Wall paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.
BATHROOM(S)	Bathroom 1	Walls	Impact damage noted. Patch and paint will generally suffice, however see a qualified plasterer for further advice
BATHROOM(S)	Bathroom 1	Flooring	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.
BATHROOM(S)	Bathroom 1	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
BATHROOM(S)	Bathroom 1	Shower And Bath	The bath tub is deteriorate. Refinish or replace. Contact a licensed plumber for recommendations and repairs
BATHROOM(S)	Bathroom 1	Shower And Bath	The taps are stiff to open. A qualified plumber should be engaged for advice and recommendations. Normally replacing spindles will rectify.
BATHROOM(S)	Bathroom 1	Shower And Bath	Possible Asbestos in shower recommendations are to have it tested to identify if and type of Asbestos maybe present.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.



KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Minor cornice cracks - Minor cornice cracks visible. Recommendations: I recommend you contact a licensed plasterer for further advice and recommendations.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Ceiling stains - No moisture readings obtained from same. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. Essentially, it is preferable to have all water damaged plaster replaced by a qualified plasterer due to potential detachment or collapse.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Ceiling	Paint flake is visible seek expert advice from a painter.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Walls	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Doors	Door / frame deterioration - General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Floor	General age, wear and tear - Recommendations: General repair and maintenance advised.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Floor	Squeaky floor boards noted. Re-fixing the floor boards may fix this issue. Seek expert advice from from a licensed builder.
KITCHEN & LAUNDRY	Kitchen and Meals Area	Sink and Taps	The taps are stiff to open - Recommendations: A qualified plumber should be engaged for repairs
KITCHEN & LAUNDRY	Kitchen and Meals Area	Cupboards And Bench Tops	Damage was noted to the bench top, contact a joinery company for repairs
KITCHEN & LAUNDRY	Kitchen and Meals Area	Cupboards And Bench Tops	Damage was noted to the cabinets, contact a joinery company for repairs
KITCHEN & LAUNDRY	Laundry Findings	Door	Laundry door / frame deterioration - Recommendations: A qualified painter should be engaged for advice and recommendations.
KITCHEN & LAUNDRY	Laundry Findings	Ceiling	General ageing and/or denting and/or wear and/or previous ceiling patching and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.
KITCHEN & LAUNDRY	Laundry Findings	Walls	General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required. Ed by a qualified plasterer due to potential detachment or collapse.
KITCHEN & LAUNDRY	Laundry Findings	Walls	Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

KITCHEN & LAUNDRY	Laundry Findings	Flooring	Borer damage to floor linings - Some weakened boards may require assessment/replacement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.
KITCHEN & LAUNDRY	Laundry Findings	Flooring	Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.
KITCHEN & LAUNDRY	Laundry Findings	Taps and Tub	General deterioration and wear to sink, cupboards and benches. Recommendations: General maintenance works required.
SUBFLOOR	Sub-Floor Observation.	Floor Timbers	Borer damage to the floor boards was observed. Recommendations: These may require replacement. See a licensed carpenter for advice and recommendations
SUBFLOOR	Sub-Floor Observation.	Piers And Foundation Walls	Ant caps are either missing or not installed. The purpose of ant capping is to prevent concealed termite entry by forcing the termites build mud tunnels around the visible sections of the ant capping enabling detection during a pest inspection. Ant Capping will not prevent the entry of termites to a structure however, correctly fitted ant caps will assist in early detection.
SUBFLOOR	Sub-Floor Observation.	Dampness	Dampness in sub floor soil. Damp sub floor soil should be avoided as it can cause fungal decay, mould and possibly footings problems. Recommendations: A qualified drainage plumber should be engaged for advice and recommendations.
SUBFLOOR	Sub-Floor Observation.	Subfloor Cleanliness	There was debris and other material in the subfloor, we recommend cleaning these to aid with ventilation and reduce the likely hood of rodents and pests.
CONCLUSION	Condition Of Inspected Structure	The Incidence of Minor Defects	The incidence of minor defects in this residential building as compared with similar buildings is considered HIGH

# PROPERTY AND INSPECTION INFORMATION

## Weather at Inspection Area

### **Weather Conditions**

The weather was raining at the time of the inspection.

## Property Information

### **Direction House Faces**

The dwelling faces East for the purposes of this inspection report.


### **Building Type**

The dwelling is a Residential House.

### **Construction Type**

The wall cladding is Brick. With Gypsum internal wall lining. ( Brick Veneer )

## BRICK VENEER WALL



### **Roof Cladding**

Tile roofing

### **Roof Design**

The roof is a Pitched roof design.

### **Storeys**

Single level dwelling

### **Property Occupied**

The home was Not Occupied.

### **Property Furnished**

The home was Not Furnished.

### **People Present**

The Estate Agent was present.

Pest Inspector was present.

Property Inspector

## **Areas Where Full Inspection Restricted**

### **Areas Inspected**

Building Exterior

Building Interior

Garage

Roof Exterior

Roof Void

Site

Subfloor

### **Area Where Inspection Was Restricted**

Building Exterior

Building Interior

Garage

Roof Void

Roof Exterior

Site

Subfloor

### **Areas Not Inspected**

Building Exterior

Building Interior

Garage

Roof Exterior

Roof Void

Site

Subfloor

## **Utility Status**

### **Water**

The water was Connected. All plumbing pipe installation should be assessed by a licensed plumber.

### **Electricity**

Electricity to the dwelling was connected. Note: We do not carry out electrical inspections for wiring or safety. This must be carried out by a licensed electrician and I recommend you have all electrical wiring and components assessed by a licensed electrician.

### **Gas**

The gas was connected at time of inspection

## **Apparent Concealment of possible defects**

### **Were apparent Concealments seen**

No apparent concealing of defects visible.

## **inspection Agreement**

### **Were there any specific requirements to The Pre Inspection Agreement**

No specific requirements to the Inspection or Pre inspection Agreement were requested by the client or their representatives.

# SITE

## Driveway

### Materials

The driveway is concrete.



### Driveway Condition

Driveway has visible tripping hazards. Repairs are required by a qualified concreter to avoid potential injury. Considered a Safety hazard

Surface raised and settled in some areas. This can cause water ponding. Relaying recommended.

The driveway is in poor condition replacement recommended. Contact a licensed concreter for a quotation.

There is evidence around the Driveway that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.



## **Paths**

### **Pathways Condition**

The concrete path is in poor condition replacement recommended.

Driveway has visible tripping hazards on paths/driveway- this may not have any affect on the structural integrity of the actual dwelling, however, repairs are required by a qualified concreter to avoid potential injury. Considered a safety hazard.

Surface raised and settled in some areas. This can cause water ponding. Relaying recommended.

There is evidence around the home paths that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.





## Fences & Gates

### **Overall Condition**

On inspection, defects were present that will require further accessing and recommendations by licensed and qualified trades persons.

Damage was noted to the timber fence. Contact a fencing contractor for repairs.

Damage to gates noted. contact a licensed fencing contractor for repairs

The gate does not latch. Have repaired by a licensed fencer.

Fence is leaning seek advice from a fence contractor.

Fungal decay is visible have a fence contractor to replace decaying fence.







## Surface Drainage

### **Drainage Findings**

There is evidence around the home paths that ponding near walls has occurred. Recommendations: A qualified landscaping contractor or a plumber should be engaged for advice and recommendations.



### **Drains**

Debris evident in/around drains - Requires cleaning out.

Gutter join is leaking seek expert advice from a licensed plumber for repair.



## Shed

### **Shed Condition**

The shed is considered in poor condition and repairs/replacement should be considered. A replacement shed should be considered.



## Trees

### Tree Findings

Trees are overhanging roof areas. Recommendations: These should be cut back away from the roof line and gutters.



# ROOF AND GUTTER

## Roof Covering

### General Disclaimer

Refer to Section 2C of the Terms And conditions section of this report

### Roof Covering Type

The roof is of concrete tiles.



### Overall Condition

On inspection, defects were noted that may require further assessment and recommendations by licensed roofer.

### Roof Clad Condition

Deterioration & ageing evident. I recommend you contact a roof restorer to clean, seal, and repoint the mortar.

Mortar cracks visible. We recommend having these repaired by a licensed roofer as they contribute to water ingress. Whilst common on properties of this age we recommend repair it may result in water ingress into the roof cavity

Tile lift/unevenness visible - Recommendations: Have roofer re-fix. Considered a minor defect but has the potential to become a Major defect if repairs aren't carried out immediately due to water ingress into the roof cavity

Moss has built up on the tiles over time. It is preferable to have removed / cleaned to prevent deterioration. Recommendations: A qualified roof restoration contractor should be engaged for advice and recommendations.

Trees overhang on roof - Recommendations: Cut back to prevent damage and blocked guttering and associated problems.

Roof line unevenness visible - Recommendations: May be related to some gaining or loosening of the burrup truss. See a carpenter for advice and recommendations. Considered a Minor Defect, however has the potential to be a costly repair.

Valley gutter mortar cracking and openings visible - Recommendations: A qualified roof restoration contractor should be engaged for advice and recommendations.

Roof valley has visible rust seek expert advice from a licensed roof plumber.

Broken Roof Tiles seek expert advice from a roof tiler.



## Flashing Conditions

Minor flashing lift/detachment - Recommendations: A qualified roofer should be engaged for repairs and recommendations.

Minor flashing rust sections - Recommendations: A qualified roofer should be engaged for repairs and recommendations.



## Guttering

### Gutter Findings

Debris in guttering areas- this requires cleaning out to prevent blocking of down pipes and leaking into eaves and fascia. Recommendations: Have gutters cleaned and assessed by a plumber for adequate fall. Also regularly clean to prevent ponding. Ponding water will contribute to rust.

There is evidence of leaking gutters. Contact a roof plumber for advice and repairs.



## Down Pipes

### **Down Pipe Findings**

Impact damage noted to down pipe. Contact a roof plumber for replacement as required.

Repair to downpipe is visible seek expert advice from a licensed plumber.





# HOT WATER SYSTEM

## Hot Water Unit

### Hot Water Unit Findings

On visual inspection the hot water suit appears dilapidated. Anticipate a replacement in the not too distant future.



### System Location

The hot water unit is located outside.

### System Type

The hot water unit is a gas storage system.

### System Make

The make of the hot water unit is rheem.

### System Year of Manufacture

Traditional storage tank water heaters have a life span of **around 10 years**. Tankless hot water systems such as instantaneous hot water systems can last up to 20 years.

## External Plumbing Pipes

### Plumbing Pipes

On Visual inspection the external plumbing pipes appear serviceable , but should be checked by a qualified plumber.

# EXTERIOR

## Weep Holes and Ventilation

### Findings

Ventilation is poor seek expert advice from a licensed builder and damp specialist for improving subfloor ventilation.



## External Door Components

### Door Findings

General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Rust in door/door frame - Recommendations: General repairs required.

Security flyscreen damage- recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Exterior Walls

### **General Disclaimer**

Refer to Section 2D of the Terms And conditions section of this report

### **Exterior Wall Material**

Brick



## Condition

Cracks noted. Possible causes may be foundation movement. Support structure deflection. Thermal movement and moisture uptake or loss, failure under external loads. In the inspectors opinion these cracks require further assessment. A structural engineer should be consulted for further evaluation and advice.

Significant lose Major defect.

Rising damp detected. A qualified damp proof specialist should be engaged for advice and recommendations. Accurate diagnosis of the cause and extent of the damp problem is very important. Note: It is imperative that specialist advice be sought to obtain accurate diagnosis of the cause and extent of the damp problem and it is advised that you have assessed prior to purchasing the dwelling as can be quite costly if a damp proof course has to be reinstated.



Significant lose Major defect.


Mortar erosion between the brickwork is eroded. Contact a licensed bricklayer for repairs.

Moisture readings to lower corse row of bricks recommended to seek expert advice from a damp course specialist to help reduce moisture.

Salt residue on rear sliding door brickwork at ground level - Salt residue is caused by poor drainage to paved area as pavers are undulating and cause ponding and surface water to this area.

Recommend seeking expert advice from a licensed builder, plumber, or skilful handyman to level out pavers and install more draining points.





## Exterior Windows

### General Disclaimer

Please refer to section 2D of the Terms And Conditions Section of this report

### Overall Condition

Gaps between window frame and wall cladding evident - This can be due to poor workmanship, wall movement, footings settlement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Lintel rust in sections. This may cause cracking in wall linings above the window - Recommendations: A qualified brick layer should be engaged for repairs and recommendations.




## Rising Damp

### **Rising Damp Findings**

High moisture readings were to the exterior walls. We recommend specialist in this field be engaged for further evaluation and repairs.

Salt residue & brick mortar deterioration on lower wall visible - Further investigation required. Recommendations: A specialist in this field should be engaged for advice and recommendations.

Salt residue on lower external wall visible - Salt residue can be associated with rising damp problems. Recommendations: Further investigation by a specialist in this field is recommended





## Damp Proof Course

A lead damp proof coursing material is visible. Lead damp proof coursing is known to break down with age when in contact with certain minerals which may be present in the brickwork or drawn up from the foundation soil. Rising damp may become a problem and the damp proof coursing material may need to be replaced.

## Eaves

### Eave Condition

Minor eave deterioration & ageing evident. Recommendations: Maintenance works, general upkeep should be carried out.

Eave lining damage visible. Recommendations: A qualified carpenter should be engaged for repairs.

We strongly recommend you re-finish and paint the eaves and timber trim to preserve same.

Possible Asbestos seek expert advice from a Asbestos company.



## **Fascia and Barge Boards**

### **Condition**

Minor deterioration & ageing evident. Recommendations: Maintenance works, general upkeep should be carried out.

Paint / finish was deteriorated in areas and is in need of maintenance - Sanding back affected areas and painting required.

Timber fungal decay (rot) visible. Recommendations: A qualified carpenter should be engaged to replace all affected timbers.

Separated on corner. Recommendations: A qualified carpenter should be engaged for advice and recommendations.





## **Porch Area**

### **Overall Condition**

Defects exist to an area or component/s requiring assessment by a specialised field. Please read below for details.



### **Ceiling Lining Condition**

Roof tiles are in poor condition require immediate replacement.

Seek expert advice from a roof tiler.



## GARAGE - CARPORT

### Garaging

#### Type

Detached garage

#### Areas Restricted

All areas could be inspected.



#### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.

#### Roof And Gutter

Down pipe/s not connected to storm water discharge - Down pipes not connected to storm water have the potential to cause differential settlement to the footings, cause rising damp and is also conducive to termite infestation. Recommendations: A qualified plumber should be engaged for advice and recommendations.

Gutter rust/penetrations - The guttering has excessive rust where leaking will occur. Recommendations: The gutters require replacement by a roof plumber to prevent further deterioration of cladding. Considered a Minor Defect

Debris visible have guttering cleaned every 6 months to prevent moisture issues.



### Wall Cladding Findings

General age deterioration. Recommendations: General repairs/maintenance as required.

Physical wall damage visible - Recommendations: Engage a licensed builder to assess/repair.

Rust is visible seek expert advice from a licensed shed specialist.



### Door Findings

General age deterioration of the garage door/components. Recommendations: General repairs/maintenance as required.

Impact damage observed. Repairs/Replacement recommended.





### Internal Wall Findings

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.



### Floor Findings

Minor hairline slab cracks - Note. Whilst these cracks appeared to be minor at the time of inspection, we strongly recommend you monitor these cracks and if worsening occurs contact a qualified concreter for further advice.



# STAIRS- PERGOLA- BALCONIES-DECKS

## Stairs & Steps

### Overall Condition

On inspection, defects were noted that may require further assessment and recommendations by licensed tradesman.

Of areas visible, major defects were evident that will require further assessing and/or repair by licensed and qualified trades persons. Please read below for details.

Of areas visible, potential safety hazards were evident that will require further assessing and/or repair by licensed and qualified trades persons, Please read below for details.



### Treads

Tripping Hazard recommend rectifying to prevent harm or injury.





## Verandah Findings

### **Overall Condition**

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



### **Veranda Floor Frame**

Cracked Concrete considered minor defect recommend to seek advice from Concreter.



## Veranda Posts

Paint Deterioration seek expert advice from painter



## General Disclaimer

Please refer to section 2G of the Terms And Conditions section of this report.

# INTERIORS

## Doors

### General Disclaimer

Please refer to section 2F of the Terms And Condition section of this report

### Front Entry Doors

Entry door / frame deterioration - General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

### Other Doors

Uneven / out of square entry door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Doors have impact Damage recommendations are to replace doors.

Door deterioration - General age has occurred to door and components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

## Entrance

### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



### Door

Door / frame deterioration - General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.



## Walls


General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Impact damage noted. Contact a licensed plasterer for repairs.



## Flooring

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## Hallways

### **Overall Condition**

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



## Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.





## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however we recommend monitor these cracks and if become wider or longer, you will need to contact a structural engineers to assess.

Impact damage noted. Contact a licensed plasterer for repairs.


Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs



## Flooring

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## **Smoke Alarm**

### **Was a Smoke Alarm Fitted**

Yes a smoke alarm was sighted but not tested.

Legislation requires smoke Alarms to be installed. Check with your local council regarding type, locations and other related requirements.



## Lounge Room

### **Overall Condition**

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



## Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.



## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Impact damage noted. Contact a licensed plasterer for repairs.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs



## Flooring

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## Dining Room

### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



### Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.



## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Impact damage noted. Contact a licensed plasterer for repairs.



## Flooring

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## Bedroom 1

### **Overall Condition**

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



### **Door**

Door / frame deterioration - General age/damage has occurred to door frame, face or components.  
Recommendations: A qualified carpenter should be engaged for advice and recommendations.





## Ceiling

Settlement Cracks Noted . These are typical and generally patch and paint will suffice, however Monitoring these cracks advised for 12 months and if become wider or longer, you will need to contact a structural engineers to assess.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.



## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Impact damage noted. Contact a licensed plasterer for repairs.



## Flooring

General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.

Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.



## Bedroom 2

### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



## Door

Door / frame deterioration - General age/damage has occurred to door frame, face or components. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Impact damage observed. Repairs / Replacement recommended



## Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.

Ceiling stains - No moisture readings obtained. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. All water damaged plaster replaced by a qualified plasterer.



## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Impact damage noted. Contact a licensed plasterer for repairs.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs



## Flooring

General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.

Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.



## **Bedroom 3**

### **Overall Condition**

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.



### **Door**

Door / frame deterioration - General age/damage has occurred to door frame, face or components.  
 Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Uneven / out of square door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Impact damage observed. Repairs / Replacement recommended



## Ceiling

General ageing and/or denting and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.

Ceiling stains - No moisture readings obtained. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. All water damaged plaster replaced by a qualified plasterer.





## Walls

General ageing and/or denting and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however we recommend monitor these cracks and if become wider or longer, you will need to contact a structural engineers to assess.

Impact damage noted. Contact a licensed plasterer for repairs.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs



## Flooring

General carpet deterioration - Recommendations: Replacement may be required A qualified carpet layer should be engaged.

Stains observed - Recommendations: Steam cleaning may rectify stained areas but they appear entrenched.

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.



## BATHROOM(S)

### Toilet Inside

#### Location

Laundry



#### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.

#### Door

Door / frame deterioration - General age/damage has occurred to door frame, face or components.  
Recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Ceiling

Settlement Cracks Noted. These are typical and generally patch and paint will suffice, however monitoring these cracks advised for 12 months and if become wider or longer, you will need to contact a structural engineers to assess.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.



## Walls

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings -  
Recommendations: A qualified painter should be engaged to assess and repair as required.

Wall paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.


Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.



## Flooring

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.

Borer damage to floor linings - Some weakened boards may require assessment/replacement.  
Recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Bathroom 1

### Location

Hall



## Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.

## Door

Door / frame deterioration - General age/damage has occurred to door frame, face or components.  
Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Uneven / out of square door frame - This can relate to some differential settlement in the footings, frame movement, age, expansion, shrinkage and the like. Recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Ceiling

General ageing and/or denting and/or wear and/or previous patching and the like is evident on ceiling linings -  
Recommendations: A qualified painter should be engaged to assess and repair as required.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

Ceiling paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.






## Walls

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Wall paint flake/deterioration is evident. Recommendations: General maintenance / painting as required.

Impact damage noted. Patch and paint will generally suffice, however see a qualified plasterer for further advice

Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.






## Flooring

Unevenness visible in floor - Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue.

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## Shower And Bath

The bath tub is deteriorate. Refinish or replace. Contact a licensed plumber for recommendations and repairs

The taps are stiff to open. A qualified plumber should be engaged for advice and recommendations. Normally replacing spindles will rectify.

Possible Asbestos in shower recommendations are to have it tested to identify if and type of Asbestos maybe present.



## Ventilation

No power connection to test.

## NOTE

All Shower areas are visually checked for leakage, but leaks often do not show except when the shower is in actual long-term use. Determining whether shower areas, bath/shower surrounds are watertight is beyond the scope of this inspection. It is very important to maintain adequate sealing in the bath areas. Very minor imperfections can allow water to get into the wall or floor areas and cause damage. Adequate and proper ongoing maintenance will be required in the future.

# KITCHEN & LAUNDRY

## Kitchen and Meals Area

### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.

General age/damage has occurred to kitchen and components. Recommendations: A qualified cabinet maker and plumber should be engaged for advice and recommendations regarding renovations



### Ceiling

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.

Minor cornice cracks - Minor cornice cracks visible. Recommendations: I recommend you contact a licensed plasterer for further advice and recommendations.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Nail popping observed to the ceiling lining. This is a Safety Hazard And should be repaired as soon as possible by a licensed plasterer to avoid any unsafe conditions.

Ceiling sagging - Requires repair from a safety perspective - Recommendations: I recommend you contact a licensed plasterer for further advice and recommendations.

Ceiling stains - No moisture readings obtained from same. Recommendations: These may have been repaired, however, you will need to monitor after a prolonged period of rainfall - If leaking persists, a qualified plumber should be engaged for advice and recommendations. Essentially, it is preferable to have all water damaged plaster replaced by a qualified plasterer due to potential detachment or collapse.

Paint flake is visible seek expert advice from a painter.



## Walls

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings -  
Recommendations: A qualified painter should be engaged to assess and repair as required.



## Doors

Door / frame deterioration - General age/damage has occurred to door frame, face or components.  
 Recommendations: A qualified carpenter should be engaged for advice and recommendations.



## Floor

General age, wear and tear - Recommendations: General repair and maintenance advised.

Borer damage to floor linings - Some weakened boards may require assessment/replacement.  
 Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Unevenness visible in floor - Floor linings may require removal to ascertain cause. Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.

Squeaky floor boards noted. Re-fixing the floor boards may fix this issue. Seek expert advice from from a licensed builder.



### **Sink and Taps**

General ageing & deterioration of the sink, cupboards and benches. Recommendations: Update kitchen.

The taps are stiff to open - Recommendations: A qualified plumber should be engaged for repairs



### Cupboards And Bench Tops

Damage was noted to the bench top, contact a joinery company for repairs

Damage was noted to the cabinets, contact a joinery company for repairs





## Laundry Findings

### General Disclaimer

Laundry appliances are not tested or moved during the inspection and the condition of any walls or flooring hidden by them cannot be judged. Drain lines and water supply valves serving washing machines are not operated.

### Restricted Areas

All areas were able to be inspected.



### Overall Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, please read below for details.

### Door

Laundry door / frame deterioration - Recommendations: A qualified painter should be engaged for advice and recommendations.



## Ceiling

General ageing and/or denting and/or wear and/or previous ceiling patching and the like is evident on ceiling linings - Recommendations: A qualified painter should be engaged to assess and repair as required.



## Walls

General ageing and/or denting and/or wear and/or previous wall patching and the like is evident on wall linings - Recommendations: A qualified painter should be engaged to assess and repair as required. Ed by a qualified plasterer due to potential detachment or collapse.

Incomplete Patch/Paint repairs noted. Call a licensed painter for repairs

Possible Asbestos recommend seeking advice from a licensed Asbestos Inspector for identifying if and type of Asbestos.



## Flooring

Unevenness visible in floor - Floor linings may require removal to ascertain cause. Recommendations: A qualified carpenter should be engaged for advice and recommendations re levelling.

Borer damage to floor linings - Some weakened boards may require assessment/replacement. Recommendations: A qualified carpenter should be engaged for advice and recommendations.

Wear & Tear is visible to flooring highly recommend a floor specialist to advise on care and maintenance to flooring for future.



## Taps and Tub

General deterioration and wear to sink, cupboards and benches. Recommendations: General maintenance works required.



# ROOF VOID

## Roof Void Findings

### General Disclaimer

Please refer to section 2B of the Terms And Conditions section of this report.

### Restricted Areas

There is insulation present in the roof space/void. This is preventing a full inspection of ceiling joists from being undertaken. It is strongly recommended that full access be gained as it could be harbouring timber pest activity, damage or defects.


There is low clearance in areas throughout the roof void which is preventing a full/thorough visual inspection taking place. It is strongly recommended that full access be granted to enable a thorough inspection to take place as it could be harbouring timber pest activity, damage or defects.

Hot water storage tank



### Roof Frame Type

The roof frame is a conventional timber frame.





### Overall Condition

Defects exist to an area or component/s requiring assessment by a specialized field. Please read below for details.

### Roof Cladding

Efflorescence observed indicating water absorption.

White stains on tile roofs are typically an efflorescence deposit and may indicate that the tile is absorbing water, thus nearing end of life. A qualified roof restorer/tiler should be engaged for advice and recommendations.

Roof tiles are in extremely poor condition and require immediate replacement.



## **Insulation**

### **Type**

The roof space is insulated with fibreglass batts.



### **Condition**

Where visible and accessible, the insulation appears to be in a serviceable condition.



# SUBFLOOR

## Access and Restrictions

### Restricted Areas

Low access restricted full visual inspection.



## Sub-Floor Observation.

### General Condition

On inspection, defects were present that will require further assessing and recommendations by licensed and qualified trades persons, for example, a structural engineer, plumber, carpenter, electrician, plasterer may need to assess. Please read below for details.



### Floor Timbers

Borer damage to the floor boards was observed. Recommendations: These may require replacement. See a licensed carpenter for advice and recommendations



## Piers And Foundation Walls

Ant caps are either missing or not installed. The purpose of ant capping is to prevent concealed termite entry by forcing the termites build mud tunnels around the visible sections of the ant capping enabling detection during a pest inspection. Ant Capping will not prevent the entry of termites to a structure however, correctly fitted ant caps will assist in early detection.

Timber fungal decay evident in stumps. Recommendations: A qualified re-stumping contractor should be engaged for advice and recommendations.

Major defect significant lose.



## Dampness

Dampness in sub floor soil. Damp sub floor soil should be avoided as it can cause fungal decay, mould and possibly footings problems. Recommendations: A qualified drainage plumber should be engaged for advice and recommendations.



## Ventilation

Inadequate ventilation observed. Additional vents or mechanical ventilation required. This may be conducive to timber decay and other damp related issues. Improvement to the ventilation is recommended. Contact a licensed builder for advise and rectification.



## Subfloor Cleanliness

There was debris and other material in the subfloor, we recommend cleaning these to aid with ventilation and reduce the likely hood of rodents and pests.



# CONCLUSION

## Condition Of Inspected Structure

### The incidence of Major Defects

The incidence of major defects in this residential building as compared with similar buildings is considered **HIGH**

### The Incidence of Minor Defects

The incidence of minor defects in this residential building as compared with similar buildings is considered **HIGH**

### The Overall Condition Of This Dwelling

The overall condition of this residential dwelling in the context of its age, type and general expectations of similar properties is **BELOW AVERAGE**



## TERMS AND CONDITIONS

The purpose of the inspection is to identify the major defects and safety hazards associated with the property at the time of the inspection. The inspection and reporting is limited to a visual assessment of the building members in accord with appendix C AS4349.1-2007. This is a general appraisal only and cannot be relied on its own, further inspections by specialist trades is strongly recommended.

### DEFINITIONS AND TERMINOLOGY

**SERVICEABLE:** The building material or component is in reasonable or serviceable condition for the age of the dwelling.

**TRADESMAN:** A defect or a number of defects were visible that will require assessment by a qualified trades person.

**AGE:** The component has deterioration due to ageing or lack of upkeep and or maintenance.

**MONITOR:** Some defects may require monitoring to ascertain if the defect will worsen, reappear or cause further problems.

**STRATA** - In the case of strata and company title properties, the inspection is limited to the interior and immediate exterior of the particular unit being inspected. This report does NOT include review of body corporate or similar records.

**HIGH:** The frequency and/or magnitude of defects are beyond the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

**TYPICAL:** The frequency and/or magnitude of defects are consistent with the inspector's expectations when compared to similar buildings of approximately the same age which have been reasonably well maintained.

**LOW:** The frequency and/or magnitude of defects are lower than the inspector's expectations when compared to similar buildings of approximately the same age that have been reasonably well maintained.

**ABOVE AVERAGE:** The overall condition is above that consistent with dwellings of approximately the same age and construction. Most items and areas are well maintained and show a reasonable standard of workmanship when compared with buildings of similar age and construction.

**AVERAGE:** The overall condition is consistent with dwellings of approximately the same age and construction. There will be areas or items requiring some repair or maintenance.

**BELOW AVERAGE:** The building and its parts show some significant defects and/or very poor non- tradesman like workmanship and/or long term neglect and/or defects requiring major repairs or reconstruction of major building.

**SIGNIFICANT ITEMS:** An item that must be reported in accordance with the scope of the inspection.

**MAJOR DEFECT:** A defect of sufficient magnitude requiring building works to avoid unsafe conditions, loss of function or further worsening of the defective item.

**MINOR DEFECT:** Any defect other than what is described as a Significant Item or major defect.

**SAFETY HAZARD:** A defect that presents unsafe conditions and must be reported as a Major defect.

**ACCESSIBLE AREA:** Is any area of the property and structures allowing the inspector safe and reasonable access within the scope of the inspection.

**LIMITATION:** A factor that prevents full or proper inspection of the building.

## IMPORTANT INFORMATION

Important information regarding the scope and limitations of the inspection and this report. Any person who relies upon the contents of this report does so acknowledging that the following clauses which define the scope and limitations of the inspection, form an integral part of the report.

The inspection comprised a visual assessment of the property to identify major defects and to form an opinion regarding the general condition of the property at the time and date of the visual inspection. An estimate of the cost of rectification of defects is outside the scope of Australian Standard AS 4349 and does not form part of this report. If the property inspected is part of a Strata or Company Title, then the inspection is limited to the interior and the immediate exterior of that particular residential dwelling. The inspection does not cover common property. This report and any other attached report should not be relied upon if the contract for sale becomes binding more than 30 days after the date of initial inspection. A re- inspection after this time is essential. Further, this report is not intended to be used as a marketing tool by and realestate agents and only the person named in the *CLIENT INFORMATION* section of the report shall this report apply to as it is assumed and agreed that the person who orders the report is indeed the person purchasing the property inspected. Where a report is ordered on behalf of a *CLIENT* it is assumed that the terms and condition and Pre Inspection Agreement have been fully explained to the *CLIENT* by the person or company ordering the report.

**We strongly advise that any cracking reported in this report should be referred to a structural engineer for further assessment and advice.**

**Acceptance Criteria:** The building shall be compared with a building that was constructed in accordance with the generally accepted practice at the time of construction and which has been maintained such that there has been no significant loss of strength and serviceability.

**Limitations:** This report is limited to a visual inspection of areas where safe and reasonable access is available and access permitted on the date and at the time of inspection. The Inspection will be carried out in accordance with AS4349.1-2007. The purpose of the inspection is to provide advice to a prospective purchaser regarding the condition of the property at the date and time of inspection. Areas for Inspection shall cover all safe and accessible areas. It does not purport to be geological as to foundation integrity or soil conditions, engineering as to structural, nor does it cover the condition of electrical, plumbing, gas or motorised appliances. It is strongly recommended that an appropriately qualified contractor check these services prior to purchase. As a matter of course, and in the interests of safety, all prospective purchasers should have an electrical report carried out by a suitably qualified contractor. This report is limited to (unless otherwise noted) the main structure on the site and any other building, structure or outbuilding within 30m of the main structure and within the site boundaries including fences.

**Safe and Reasonable Access:** Only areas to which safe and reasonable access is available were inspected. The Australian Standard AS4349.1 defines reasonable access as "areas where safe, unobstructed access " is provided and the minimum clearances specified below are available, or where these clearances are not available, areas within the inspector's unobstructed line of sight and within arm's length. Reasonable access does not include removing screws and bolts to access covers. Reasonable access does not include the use of destructive or invasive inspection methods and does not include cutting or making access traps or moving heavy furniture, floor coverings or stored goods.

Roof Interior- Access opening = 400 x 500 mm - Crawl Space = 600 x 600mm - Height accessible from a 3.6m ladder.

Roof Exterior- Must be accessible from a 3.6m ladder placed on the ground.



**1) NOT A CERTIFICATE OF COMPLIANCE:** This report is not an all encompassing report dealing with the building from every aspect. It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the inspection. Whether or not, a defect is considered significant or not depends too a large extent, upon the age and type of the building inspected. This report is not a certificate of compliance with the requirements of any act, regulation, ordinance or by-law. It is not a structural report. Should you require any advice of a structural nature you should contact a structural engineer.

**2) VISUAL INSPECTION:** This is a visual inspection only limited to those areas and sections of the property fully accessible and visible to the inspector on the date of inspection.

**2A) Please refer to each individual area regarding sections that were incapable or being inspected. Please acknowledge the following.** Where a complete inspection of some areas listed through the report may not have been physically possible (due to but not limited to - storage, furniture, beds, personal belongings in cupboards and/or wardrobes, the 2nd storey roofing, gutters, fascia, flashings and the like, low clearance in sub floor or roof void areas, ducts and deep insulation restricting access in roof voids, sub floor restrictions including plumbing, ducts, low clearance, no access doors or access doors too small and the like) then it follows that defects, timber pest activity and/or damage may exist in these areas. To adequately inspect these restricted areas, ducts and floor boards may need to be removed, furniture moved, cupboards and wardrobes emptied which will be difficult to carry out. This will obviously be difficult to carry out due to time restrictions and permission would need to be obtained from the property owner.

This Firm DOES NOT GUARANTEE IN ANY WAY that there ARE OR ARE NOT any defects, termite damage or live termites in any areas NOT ABLE to be inspected. To obtain a full understanding of the report findings, it is essential you read the entire inspection report, including the information sections at the end of this report and I encourage you to call me if you have any queries at all before purchasing the inspected dwelling.

**2B)** Entering attics or roof voids that are heavily insulated can cause damage to the insulation and attic framing. Attics with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. In such cases, the attic is only partially accessed, thereby limiting the review of the attic area from the hatch area only. Inspectors will not crawl the attic area when they believe it is a danger to them or that they might damage the attic insulation or framing. There is a limited review of the attic area viewed from the hatch only in these circumstances.

**2C)** The roof covering will not be walked upon if in the opinion of the inspector it is not safe to do so. Generally issues that prevent roof access include, access height over 3 metres, steep pitch, wet/slippery surfaces, deteriorated covering. Not being able to walk a roof significantly limits our inspection which can result in hidden defects going undetected. The overall condition of the roofing and its components is an opinion of the general quality and condition of the roofing material. The inspector cannot and does not offer an opinion or warranty as to whether the roof leaks or may be subject to future leakage. This report is issued in consideration of the foregoing disclaimer. The only way to determine whether a roof is absolutely water tight is to observe it during a prolonged rainfall. Many times, this situation is not present during the inspection. We offer no guarantee that the roof cladding or roof components such as flashing will not leak in the future.

**2D) Limitations of the exterior inspection.** This is a visual inspection limited in scope by (but not restricted to) the following conditions: A representative sample of exterior components was inspected rather than every occurrence of components. The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards. Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawalls, break-walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report. Please note - If any wall cracking/cracks/openings are found at this dwelling, we cannot offer any guarantee that any visible wall cracks will not widen or lengthen over time or in the future as this is impossible to predict. We strongly recommend you contact a practicing structural engineer for further advice.

2E) Timber framed windows can bind or stick. This can be seasonal due to the fluctuation in moisture content in timber. If binding or sticking continues minor adjustments may be required by a carpenter. Binding windows is not normally a major defect, however in some circumstances binding windows and doors can be directly related to some differential footings settlement. If any timber fungal decay on frames or deteriorated putty seals is noted, the consultant will not attempt to operate windows due to potential damage. Windows that are sticking, binding or paint stuck will also not be forced open. Water leaks to Windows and surrounds can not be determined in the absence of rain.

2F) Internal Inspections. Inspection to the upper-side of flooring of the internal inspection is normally restricted by carpets and or other floor coverings, cupboards/cabinets, joinery, finishes and fittings. Defects or timber pest damage may be present and not detected in areas where inspection was limited, obstructed or access was not gained. The condition of walls behind wall coverings, paneling and furnishings cannot be inspected or reported on. Only the general condition of visible areas is included in this inspection.

Where fitted. Wood burning and other forms of fireboxes are outside the scope of this inspection. We recommend you have these tested prior to purchase for peace of mind.

2G) Important note: Where any elevated structure (deck, balcony, veranda etc) is present, and this elevated structure is designed to accommodate people, you must have this structure checked by an engineer or other suitably qualified person. You should also arrange annual inspections of the structure by an engineer or other suitably qualified person to ensure any maintenance that may become necessary is identified. Care must be taken not to overload the structure. Nothing contained in this inspection should be taken as an indicator that we have assessed any elevated structure as suitable for any specific number of people or purpose. This can only be done by a qualified engineer. For the purpose of this report, the structure includes elevated decks, verandas, pergolas, balconies, handrails, stairs and children's play areas. Where any structural component of such a structure is concealed by lining materials or other obstructions, these linings or obstructions must be removed to enable an evaluation to be carried out by an appropriately qualified person.

3) **CONCEALED DEFECTS:** This report does not and cannot make comment upon: Defects that may have been concealed the assessment or detection of defects (including rising damp and leaks) which may be subject to the prevailing weather conditions whether or not services have been used for some time prior to the inspection and whether this will affect the detection of leaks or other defects (eg. In the case of shower enclosures and bath tubs, the absence of any leaks or dampness at the time of the inspection does not necessarily mean that the enclosure will not leak after use) the presence or absence of timber pests; gas-fittings; common property areas; environmental concerns; the proximity of the property to flight paths, railways, or busy traffic; noise levels; health and safety issues; heritage concerns; security concerns; fire protection; site drainage (apart from surface water drainage); swimming pools and spas (non-structural); detection and identification of illegal building work; detection and identification of illegal plumbing work; durability of exposed finishes; neighborhood problems; document analysis; electrical installation; any matters that are solely regulated by statute; any area(s) or item(s) that could not be inspected by the consultant.

4) **NO GUARANTEE:** Accordingly this report is not a guarantee that defects and/or damage does not exist in any inaccessible or partly inaccessible areas or sections of the property. Such matters may upon request be covered under the terms of a special purpose property report.

5) **SWIMMING POOLS:** Swimming pools/spas are not part of the standard building report under as4349.1-2007 And are not covered by this report. We strongly recommend a pool expert should be consulted to examine the pool and the pool equipment and plumbing as well as the requirements to meet the standard for pool fencing. Failure to conduct this inspection and put into place the necessary recommendations could result in finds for non compliance under the legislation.

6) **SURFACE WATER AND DRAINAGE:** The retention of water from surface run off could have an effect on the foundation material which in turn could affect the footings to the house. Best practice is to monitor the flow of surface water and storm water run off and have the water directed away from the house or to storm water pipes by a licensed drainage plumber. The general adequacy of site drainage is not included in the standard property inspection report. Comments on surface water drainage are limited as where there has been either little or no rainfall for a period of time, surface water drainage may appear to be adequate but then during periods of heavy rain, may be found to be inadequate. Any comments made in this report are relevant only to the conditions present at the time of inspection. It is recommended that a smoke test be obtained to determine any illegal connections, blocked or broken drains.

7) **SHOWER RECESSES:** Tests may be made on shower recesses to detect leaks (if water is connected). The tests may not reveal leaks or show incorrect waterproofing if silicone liquid or masonry sealant has been applied prior to the inspection. Such application is a temporary waterproofing measure and may last for some months before breaking down. The tests on the shower recesses are limited to running water within the recesses and visually checking for leaks. As showers are only checked for a short period of time, prolonged use may reveal leaks that were not detected at the time of inspection. No evidence of a current leak during inspection does not necessarily mean that the shower does not leak.

8) **GLASS CAUTION:** Glazing in older houses (built before 1978) may not necessarily comply with current glass safety standards AS1288. In the interests of safety, glass panes in doors and windows especially in traffic-able areas should be replaced with safety glass or have shatterproof film installed unless they already comply with the current standard.

9) **STAIRS AND BALUSTRADES:** Specifications have been laid down by the Australian Building Code – Section 3.9 covering stairs, landings, balustrades to ensure the safety of all occupants and visitors in a building. Many balustrades and stairs built before 1996 may not comply with the current standard. You must upgrade all such items to the current standard to improve safety.

10) **RETAINING WALLS:** Where retaining walls are more than 700mm high these wall/s should have been installed with engineering design and supervision. Walls found on the site were not assessed and the performance of these walls is not the subject of a standard property report and should be further investigated with regard to the following items, adequate drainage systems, adequate load bearing, correct component sizing and batter.

11) **ROOMS BELOW GROUND LEVEL:** If there are any rooms under the house or below ground level (whether they be habitable or non-habitable rooms), these may be subject to dampness and water penetration. Drains are not always installed correctly or could be blocked. It is common to have damp problems and water entry into these types of rooms, especially during periods of heavy rainfall and this may not be evident upon initial inspection. These rooms may not have council approval. The purchaser should make their own enquiries with the Council to ascertain if approval was given.

12) **ASBESTOS DISCLAIMER :** No inspection for asbestos was carried out at the property and no report on the presence or absence of asbestos is provided.

13) **MOULD** (mildew and non-wood decay fungi) disclaimer: Mildew and non wood decay fungi is commonly known as mould. However, mould and their spores may cause health problems or allergic reactions such as asthma and dermatitis in some people. No inspection for mould was carried out at the property and no report on the presence or absence of mould is provided.

14) **MAGNESITE DISCLAIMER:** No inspection for magnesite flooring was carried out at the property and no report on the presence or absence of magnesite flooring is provided. You should ask the owner whether magnesite flooring is present and/or seek advice from a structural engineer.

15) **ESTIMATING DISCLAIMER:** No estimate is provided in this report. We strongly recommend you obtain quotes for repairs from licensed tradesman prior to a decision to purchase.

16) **DISCLAIMER OF LIABILITY:** No liability shall be accepted on an account of failure of the report to notify any problems in the area(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the inspector (including but not limited to or any area(s) or section(s) so specified by the report) Compensation will only be payable for losses arising in contract or tort sustained by the client named on the front of this report. Compensation is limited to the price of the report initially paid by the claimant named in the report as the "*CLIENT*"

17) **DISCLAIMER OF LIABILITY TO THIRD PARTIES:** Compensation will only be payable for losses arising in contract or tort sustained by the Client named on the front of this report. Any third party acting or relying on this Report, in whole or in part, does so entirely at their own risk.

18) **COMPLAINTS PROCEDURE:** In the event of any dispute or claim arising out of, or relating to the Inspection or the Report, or any alleged negligent act or omission on Our part or on the part of the individual conducting the Inspection, either party may give written Notice of the dispute or claim to the other party. If the dispute is not resolved within twenty one (21) days from the service of the written Notice then either party may refer the dispute or claim to a mediator nominated by Us. The cost shall be met equally by both parties or as agreed as part of the mediated settlement. Should the dispute or claim not be resolved by mediation then one or other of the parties may refer the dispute or claim to the Institute of Arbitrators and Mediators of Australia who will appoint an Arbitrator who will resolve the dispute by arbitration. The Arbitrator will also determine what costs each of the parties are to pay.

## OTHER RECOMMENDED INSPECTIONS

Electrical installation: All electrical wiring, meter-box and appliances need to be checked by a qualified electrician. The inspection of any electrical item is outside the scope of this report.

Plumbing: All plumbing needs to be inspected and reported on by a plumber.

Hot water service: All hot water services need to be inspected and reported on by a plumber and/or electrician.

Gas: All gas services need to be inspected and reported on by a gas plumber.

Phone: All phones, phone lines and outlets need to be inspected and reported on by a telecommunications technician.

Smoke Alarm: Australian standard AS3786 advises that smoke alarms are required for all buildings where people sleep. It is recommended that an electrician be consulted to give advice on those installed or to install smoke alarms.

The septic tanks: Should be inspected by a licensed plumber.

Trees: Where trees are too close to the house this could affect the performance of the footing as the moisture levels change in the ground.

## Contact the inspector

Please feel free to contact the inspector who carried out this inspection. Often it is very difficult to fully explain situations, problems, access difficulties, building faults or their importance in a manner that is readily understandable by the reader. Should you have any difficulty in understanding anything contained within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

## TIMBER PEST INSPECTION

Please note that this inspection and report was a Visual only inspection to the readily accessible areas of the property as defined within the terms and conditions of this report.

Please ensure that you read all sections of the report as well as the additional information at the rear of the report and understand the limitations and the special recommendations for this construction style. If there is something you do not understand or require further clarification. Please contact the Inspector.

### IMPORTANT NOTE:

The Client acknowledges that, unless stated otherwise, the Client as a matter of urgency should implement any recommendation or advice given in this Report.

The Summary is not the Report. The following Report must be read in full in conjunction with the Summary. If there is a discrepancy between the information provided in the Summary and that contained within the body of the Report, the information in the body of the Report shall override the Summary.

# ACCESS AND RESTRICTIONS

## Note

### **Inspection Information**

For the purpose of visual timber pest inspection this timber pest inspection report which form part of a combined timber pest and building inspection.

The inspection information listed at the beginning of the building inspection report namely report information shall apply. Including the date and time of inspection, agreement number, who the report is prepared for and the description of the property inspected. THIS IS A VISUAL INSPECTION ONLY in accord with the requirements of AS4349.3-2010 - Inspection of buildings Part 3: Timber Pest Inspections.

## Summary Only

### **Important Disclaimer**

Important disclaimer

This summary and the opinion is supplied to allow a quick and superficial overview of the inspection results. This summary is not the report and cannot be relied upon on its own. This summary must be read in conjunction with the full report and not in isolation from the report. If there should happen to be any discrepancy between anything in the report and anything in this summary, the information in the report shall override that in this summary. The report is subject to terms and limitations.

Note: It is essential that you read the entire report; other inspectors may have and are entitled to different opinions in relation to this dwelling.

Note: This report should not be relied upon if the contract for sale becomes binding more than 30 days after the date of initial inspection. A re-inspection after this time is essential

## 1.1 Access to Areas

### **Areas where Access Should be Gained**

Yes. Please read the report in its entirety

## 1.2 Timber Pest Activity

### **Was there any Termite Workings or Damage Found**

No - Of the areas able to be inspected there were no termite workings or termite damage visible. Please read this report in its entirety.

### **Were Any Live or Active Termites Found**

No. Please read the report in its entirety

## **NOTE**

Note: Any evidence of termite activity or workings in the grounds or building structure assumes that risk to buildings is very high. We strongly recommend a treatment to eradicate the termites and to protect the building.

### **Any Visible Borer of seasoned Timbers Found**

Yes - Read this report in its entirety.

### **Any Damage caused by Wood Decay, Rot Found**

Yes - Read this report in its entirety.

## NOTE

For complete and accurate information please refer to the attached complete visual timber pest report, provided in accord with as 4349.3

### **Are further inspections recommended**

YES - read this report in its entirety.

### **Where any major safety hazards identified**

NO - read this report in its entirety

### **Susceptibility of this property to timber pests**

In our opinion, the susceptibility of this property to timber pests is considered to HIGH. Read the report in full.

### **Is a Invasive Inspection Recommended**

Yes

## **1.3 Brief Description of the Structure Inspected**

### **Building Type**

Free Standing Domestic House

### **Height**

Single Storey

### **Floor**

Timber Flooring on Brick Piers

### **Walls**

Gypsum Lined Walls

### **Garage**

Detached metal frame

### **Roof**

Pitched Tile

### **Fences**

Timber Fencing.

### **Out Buildings**

Out Building.

## Terms and Limitations

### Important Information

Any person who relies upon the contents of this report does so acknowledging that the following clauses which define the scope and limitations of the inspection form an integral part of the report.

1. This is a visual inspection only in accord with the requirements of as 4349.3 Inspection of buildings part 3: Timber pest inspections. This visual inspection was limited to those areas and sections of the property to which reasonable access (see definition) was both available and permitted on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, inside the eaves, behind stored goods in cupboards, in other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. An invasive inspection will not be performed unless a separate contract is entered into. In an occupied property it must be understood that furnishings or household items may be concealing evidence of timber pests which may only be revealed when the items are moved or removed. In the case of strata type properties only the interior of the unit is inspected.

2. Scope of report: This report is confined to reporting on the discovery, or non-discovery, of infestation and/or damage caused by subterranean and dampwood termites (white ants), borers of seasoned timber and wood decay fungi (hereinafter referred to as "timber pests"), present on the date of the inspection. The inspection did not cover any other pests and this report does not comment on them. Dry wood termites (family: Kalotermitidae) and european house borer (hylotrupes bujulus linnaeus) were excluded from the inspection, but have been reported on if, in the course of the inspection, any visual evidence of infestation happened to be found. If cryptotermes brevis (west indian dry wood termite) or hylotrupes bujulus linnaeus are discovered we are required by law to notify government authorities. If reported a special purpose report may be necessary.

3. Hidden damage: If timber pest activity and/or damage is found, within the structures or the grounds of the property, then damage may exist in concealed areas, eg framing timbers. An invasive inspection is strongly recommended in this case. Damage may only be found when wall linings, cladding or insulation are removed to reveal previously concealed timbers.

4. Limitations: Nothing contained in the report implies that any inaccessible or partly inaccessible areas or sections of the property being inspected by the inspector on the date of the inspection were not, or have not been, infested by timber pests. Accordingly this report is not a guarantee that an infestation and/or damage does not exist in any inaccessible or partly inaccessible areas or sections of the property. Nor is it a guarantee that a future infestation of timber pests will not occur or be found.

5. Determining extent of damage: The report is not a structural damage report. Any observations or recommendations about timber damage should not be taken as expert opinion and cannot be relied upon. The report will not state the full extent of any timber pest damage. The report will state timber damage found as 'slight', 'moderate', 'moderate to extensive' or 'extensive'. This information is not the opinion of an expert. If any evidence of timber pest activity and/or damage resulting from timber pest activity is reported either in the structure(s) or the grounds of the property, then you must assume that there may be concealed structural damage within the building(s). This concealed damage may only be found when wall linings, cladding or insulation is removed to reveal previously concealed timbers. An invasive timber pest inspection (for which a separate contract is required) is strongly recommended and you should arrange for a separate inspection by a qualified builder, engineer, or architect to carry out a structural inspection and to determine the full extent of the damage and the extent of repairs that may be required. You agree that neither we nor the individual conducting the inspection is responsible or liable for the repair of any damage whether disclosed by the report or not.



6. Mould: Mildew and non-wood decay fungi is commonly known as mould and is not considered a timber pest. However, mould and their spores may cause health problems or allergic reactions such as asthma and dermatitis in some people. No inspection for mould was carried out at the property and

No report on the presence or absence of mould is provided. Should any evidence of mould happen to be noticed during the inspection, it will be noted in the other information (5.11) Section of this report. If mould is noted as present within the property and you are concerned as to the possible health risk resulting from its presence then you should seek advice from your local council, state or commonwealth government health department or a qualified expert such as an industry hygienist.

7. Disclaimer of liability: No liability shall be accepted on account of failure of the report to notify any termite activity and/or damage present at or prior to the date of the report in any areas(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the licensed inspector (including but not limited to any area(s) or section(s) so specified by the report).

8. Disclaimer of liability to third parties: Compensation will only be payable for losses arising in contract or tort sustained by the client named on the front of this report. Any third party acting or relying on this report, in whole or in part, does so entirely at their own risk.

9. Complaints procedure: In the event of any dispute or claim arising out of, or relating to the inspection or the report, you must notify us as soon as possible of the dispute or claim by email, fax or mail. You must allow us (which includes persons nominated by us) to visit the property (which visit must occur within twenty eight (28) days of your notification to us) and give us full access in order that we may fully investigate the complaint. You will be provided with a written response to your dispute or claim within twenty eight (28) days of the date of the inspection.

If you are not satisfied with our response you must within twenty one (21) days of your receipt of our written response refer the matter to a mediator nominated by us from the institute of arbitrators and mediators of australia. The cost of the mediator will be borne equally by both parties or as agreed as part of the mediated settlement.

Should the dispute or claim not be resolved by mediation then the dispute or claim will proceed to arbitration. The institute of arbitrators and mediators of australia will appoint an arbitrator who will hear and resolve the dispute. The arbitration, subject to any directions of the arbitrator, will proceed in the following manner:

A) the parties must submit all written submissions and evidence to the arbitrator within twenty one (21) days of the appointment of the arbitrator; and

(B) the arbitration will be held within twenty one (21) days of the arbitrator receiving the written submissions.

The arbitrator will make a decision determining the dispute or claim within twenty one (21) of the final day of the arbitration. The arbitrator may, as part of his determination, determine what costs, if any, each of the parties are to pay and the time by which the parties must be paid any settlement or costs. The decision of the arbitrator is final and binding on both parties. Should the arbitrator order either party to pay any settlement amount or costs to the other party but not specify a time for payment then such payment shall be made within twenty one (21) days of the order.

In the event you do not comply with the above complaints procedure and commence litigation against us then you agree to fully indemnify us against any awards, costs, legal fees and expenses incurred by us in having your litigation set aside or adjourned to permit the foregoing complaints procedure to complete.

9. Complaint investigation: In the event any litigation is started as a result of the inspection and/or report, you indemnify us against any legal fees and expenses incurred where you have not first allowed us the opportunity to visit the property to investigate the complaint and provide you with a written response within 28 days.

## **2. Visual Timber Pest Inspection Report**

### **Important Information**

For complete and accurate information please refer to the attached complete visual timber pest report, provided in accord with AS 4349.3

### **2.1 Brief Description of Areas Inspected**

#### **NOTE**

Only structures, fences & or trees within 30m of the building but within the property boundaries were inspected.

#### **The areas inspected were**

Exterior  
Fences  
Garage  
Grounds  
Interior  
Outbuildings  
Roof Void  
Subfloor

### **2.2 Areas Not Inspected**

#### **Please Note**

No inspection was made, and no report is submitted, of inaccessible areas. These include, but may not be limited to, cavity walls, concealed frame timbers, eaves, flat roofs, fully enclosed patios sub-floors, soil concealed by concrete floors, fireplace hearths, wall linings, landscaping, rubbish, floor coverings, furniture, pictures, appliances, stored items, insulation, hollow blocks/posts, etc.

The inspection did not include obstructed areas, not readily accessible and inaccessible areas at the time of inspection which were inaccessible, not readily accessible or obstructed areas at the time of inspection. Locked and restricted areas were not inspected. Removing furnishings and obstructions which may be concealing evidence of defects is outside the scope of this inspection. It is strongly recommended that all obstructions be removed and full access be provided as defects may exist in these areas.

#### **Unable to Inspect**

No entire access to roof space sections.

No entire access was available to the sub floor.

### **2.3 Reasonable Access Areas Not Available and Why**

#### **Roof Void Because**

Low clearance in sections of roof void restricted reasonable access to the roof space.

Note: Important Limitations for Safe and Reasonable Access

Only areas where reasonable access was available were inspected. AS 4349.3 defines reasonable access and states that access will not be available where there are safety concerns, or obstructions, or the space available is less than the following:

ROOF VOID - the dimensions of the access hole must be at least 450mm x 400mm, and, reachable by a 2.1M step ladder or 3.6M ladder, and, there is at least 600mm x 600mm of space to crawl;

ROOF EXTERIOR - must be accessible by a 3.6M ladder

Reasonable access does not include the use of destructive or invasive inspection methods. Nor does reasonable access include cutting or making access traps, or moving heavy furniture or stored goods.

Bulk insulation restricting view of roofing timbers.

## **Sub Floor Due To**

Parts of subfloor access were to low.

## **Reasonable Access**

**Note:** The Australian standard AS3660 refers to AS4349.3-2010 Which defines reasonable access. Access will not be available where there are safety concerns, or obstructions, or the space available is less than the following: Subfloor - Access is normally not available where dimensions are less than 500mm x 400mm for the access hole and less than 400mm of crawl space beneath the lowest bearer, or, less than 500mm beneath the lowest part of any concrete floor.

It is strongly recommended that full access be granted to enable a thorough inspection to take place as it could be harboring timber pest activity and/or damage.

Please note since a complete inspection of the above areas was not possible, timber pest activity and/or damage may exist in these areas.

It is strongly recommended that full access be granted to enable a thorough inspection to take place as it could be harboring timber pest activity and/or damage.

## **2.4 Areas of Visual Inspection obstructed and why.**

### **Areas Obstructed**

Where present carpet conceals damage to the underside, present throughout the building which is preventing a thorough inspection from being undertaken. You should be aware that furnishings and/or owners possessions may be concealing evidence of timber pests and defects, which may only be revealed when items are removed or moved. It is strongly recommended that full access be gained as it could be harbouring timber pest activity, pest damage or defects.

There is low clearance in areas throughout the roof void which is preventing a full/thorough visual inspection taking place. It is strongly recommended that full access be granted to enable a thorough inspection ,and could be harbouring timber pest activity and/or damage.

There is insulation, present in the roof space/void. This is preventing a full inspection from being undertaken. It is strongly recommended that full access be gained as it could be harbouring timber pest activity and/or damage.

There is low clearance in areas present throughout the subfloor which is preventing a full/thorough visual inspection taking place. It is strongly recommended that full access be granted to enable a thorough inspection to take place as it could be harbouring timber pest activity and/or damage.

### **Please Note**

Please note since a complete inspection of the above areas was not possible, timber pest activity and/or damage may exist in these areas.

## **2.5 High Risk Areas where access should be gained**

### **Areas of High Risk requiring Inspection**

Areas of high risk area(s) to which access should be gained, or fully gained, since they may show evidence of timber pests or damage:

## High Risk Areas are

The roof space top plates around the perimeter walls could not be fully accessed. Termites or termite damage may exist. Access must be made available to full inspect this area.

The sub floor space could not be fully accessed, termites or termite damage may exist. Access must be made available to full inspect this area.

Important: If a complete inspection of the above areas was not possible, timber pest activity and/or damage may exist in these areas.

Further Inspections are strongly recommended to areas where Reasonable Access is Unavailable, Obstructed or Restricted or a High Risk of possible Timber Pests and /or Damage exists.

## The following further inspections are recommended

Remove Bulk Insulation and re-inspect

We strongly recommend that full Access be provided and a re-inspection be conducted prior to a decision to purchase

Furnished properties: Where a property is furnished at the time of the inspection the furnishings and stored goods may be concealing evidence of Timber Pest Activity. This evidence may only be revealed when the property is vacated. A further inspection of the vacant property is strongly recommended in this case.

## 2.6 House furnishings

### Please Note

Where a property is furnished at the time of the inspection then you must understand that the furnishings and stored goods may be concealing evidence of timber pest activity. This evidence may only be revealed when the property is vacated. A further inspection of the vacant property is strongly recommended in this case.

No inspection was made and no report is submitted, of inaccessible areas. If a complete inspection of the areas in the dwelling was not possible, termite activity and/or damage may exist in these areas and nothing in this report implies that any inaccessible or partly inaccessible areas or sections of the property being inspected by me on the date of the inspection were not, or have not been infested by timber pests.

Accordingly, this report is does not report on inaccessible areas. This includes but may not be limited to concealed frame timbers, eaves, areas concealed by concrete floors, wall linings, soil, landscaping, rubbish, floor coverings (carpet lino etc.), Furniture, pictures, appliances (dishwashers, refrigerators, washing machines, ovens, microwave ovens, heating and cooling units etc.), Stored items (clothes on floor, boxes on floor and against walls, beds against walls and the like), insulation, hollow blocks/columns/posts/poles or other architectural hollow structures. Furnishings found at this dwelling were not inspected and do not form part of this inspection.

## Was the dwelling Furnished

The dwelling was not fully furnished.

## TIMBER PEST FINDINGS

### **3. Subterranean Termites**

#### **Were Active or Live Termites Visible**

No. Of the visible and accessible areas inspected, there were no visible termites found at the time of the inspection.

### **3.1 Termite Nests**

#### **Was a Termite Nest Found**

No termite nests found at time of inspection.

### **3.2 Subterranean Termite Damage or workings**

#### **Any workings or damage found**

No. Of the visible and accessible areas inspected, no termite working or timber damage found at the time of the inspection.

#### **Please Note**

Where evidence of termite activity was found in the grounds then the risk to buildings is very high. A treatment to eradicate the termites and to protect the building(s) should be carried out. Where the evidence of termite workings was found in the grounds or the building(s) then the risk of a further attack is very high.

#### **Was any evidence of timber damage visible**

We claim no expertise in building and if any evidence or damage has been reported then you must have a building expert determine the full extent of damage and the estimated cost of repairs or timber replacement (See Terms & Limitations).

#### **If damage is visible does it present a safety risk**

Important Note: Where a Major Safety Hazard is identified above, it must be attended to and/or rectified to avoid the possibility of personal injury &/or death.

**VERY Important:**

If live termites or any evidence of termite workings or damage was reported above within the building(s) or in the ground and fences then it must be assumed that there may be concealed termite activity and/or timber damage. This concealed activity or damage may only be found when alterations are carried out such as when wall linings, cladding or insulation are removed or if you arrange for an invasive inspection. We claim no expertise in structural engineering or building. We strongly recommend that you have a qualified person such as a Builder, Engineer, Architect or other qualified expert in the building trade determine the full extent of the damage, if any. This may require an invasive inspection. We take no responsibility for the repair of any damage whether disclosed by this report or not. (See Terms & Limitations).

Where visual evidence of termite workings and/or damage is reported above, but no live termites were present at the time of inspection, you must realize that it is possible that termites are still active in the immediate vicinity and the termites may continue to cause further damage. It is not possible, without benefit of further investigation and a number of inspections over a period of time, to ascertain whether any infestation is active or inactive. Active termites may simply have not been present at the time of inspection due to a prior disturbance, climatic conditions, or they may have been utilizing an alternative feeding source. Continued, regular, inspections are essential. Unless written evidence of a termite protection program in accord with "Australian Standard 3660" with ongoing inspections is provided, you must arrange for a treatment in accord with "Australian Standard 3660" to be carried out immediately to reduce the risk of further attack.

General remarks: A more thorough INVASIVE INSPECTION is available (refer to section 9). Where any current visible evidence of Timber Pest activity is found it is strongly recommended that a more invasive inspection is performed. Trees and stumps on the property with a diameter more than 100mm have been visually inspected for evidence of termite activity to a height of 2m where access was possible and practical. It is very difficult, and generally impossible to locate termite nests since they are underground and evidence in trees is usually well concealed. We therefore strongly recommend that you arrange to have trees test drilled for evidence of termite nests.

### **3.3 Any Evidence of a Previous Termite Treatment**

#### **Any Evidence of previous Treatments Found**

No, there was no visible evidence or a previous termite treatment was located at the property.

#### **Warning**

Warning: If evidence of drill holes in concrete or brickwork or other signs of a possible previous treatment are reported then the treatment was probably carried out because of an active termite attack. Extensive structural damage may exist in concealed areas. You should have an invasive inspection carried out and have a builder determine the full extent of any damage and the estimated cost of repairs as the damage may only be found when wall linings etc. are removed. Normally if a termite treatment has been carried out then a durable notice should be located in the meter box indicating the type of termite shield system, treated zone or combination has been installed.

### **3.4 Durable Notice**

#### **Was a Treatment Notice Found**

No, a durable notice was not found during the inspection.

#### **Please Note**

This firm can give no assurances with regard to work that may have been previously performed by other firms. You should obtain copies of all paperwork and make your own inquiries as to the quality of the treatment, when it was carried out and warranty information. In most cases you should arrange for a treatment in accord with "australian standard 3660" be carried out to reduce the risk of further attack.

### **3.5 Timber Fungal Decay - Rot**

#### **Evidence of Wood Decay Fungi -Rot**

Yes, in the following areas ,  
Fascia and / or Barge board  
Window frame/s ,  
Door frames



#### **Extent of Damage Caused by Rot**

Extent of rot damage is considered moderate to high

If any evidence of fungal decay or damage is reported you should consult a building expert determine the full extent of damage and the estimated cost of repairs or timber replacement (see terms & limitations).

#### **Does the damage present a Major Safety Hazard**

No

Important Note: Where a Major Safety Hazard is identified above, it must be attended to and/or rectified to avoid the possibility of personal injury &/or death.

We claim no expertise in building and if any evidence of fungal decay or damage is reported you should consult a building expert to determine the full extent of damage and the estimated cost of repairs or timber replacement.

## **3.6 Borer Findings**

### **Borer Information**

Borer information: *Lyctus brunneus* (powder post beetle) is not considered a significant pest of timber. Damage is confined to the sapwood so treatment or timber replacement is not usually required. However, you should have a building expert investigate if any timber replacement is required.

*Anobium punctatum* (furniture beetle) and *calymmaderus incisus* (queensland pine beetle) must always be considered active, unless proof of treatment is provided, because, unless the timber is ground up, one cannot determine conclusively if activity has ceased. Total timber replacement of all susceptible timbers is recommended. A secondary choice is treatment. However, the evidence and damage will remain and the treatment may need to be carried out each year for up to three years.

### **Was Visible Evidence of Borer Found**

Yes, *lyctus brunneus* was found- commonly known as the powder post beetle.

Large Timber pest infestation visible seek expert advice from a licensed builder for non-susceptible Timbers.

Major defect.



### **Moderate Damage was Found in**

Floor boards





### **Please Note**

If any evidence or damage has been reported then you must have a building expert determine the full extent of damage and the estimated cost of repairs or timber replacement (see terms & limitations). Borer activity is usually determined by the presence of exit holes and/or frass. Since a delay exists between the time of initial infestation and the appearance of these signs, it is possible that some borer activity may exist that is not discernible at the time of inspection.

### **3.7 Borer Recommendations**

#### **Borer Recommendations**

Note: Only lyctus borer/powder post borer, pin-hole borer and furniture beetle presence is inspected.

Replacement of all susceptible timbers is always preferred since, in the event of selling the property in the future it is probable that an inspector will report the borers as active (see above). A chemical treatment to control and/or protect against furniture beetle and/or queensland pine beetle can be considered as a less effective, lower cost option. Before considering this option you should consult with a builder (see terms & limitations) to determine if the timbers are structurally sound. Following the initial treatment a further inspection is essential in twelve months' time to determine if further treatment is needed. Treatments over a number of consecutive years may be required.

## CONDUCTIVE CONDITIONS

### 4. Conducive Conditions to Timber Pests

#### Water leaks

There was water leakage detected during the inspection from some gutter joins.

Downpipe Base is broken seek immediate advice from a licensed plumber for immediate repair.



#### Please Note

Water leaks, especially in or into the sub-floor or against the external walls ie: Leaking taps, water tanks or down pipes and or guttering, increases the likelihood of termite attack. Leaking showers or leaks from other „wet areas“ also increase the likelihood of concealed termite attack. These conditions are also conducive to borer activity and wood decay.

If any leaks were reported then you must have a plumber or other building expert to determine the full extent of damage and the estimated cost of repairs.

### 4.1 Hot Water Unit Overflow

#### Please Note

Hot water services and air conditioning units which release water alongside or near to building walls need to be connected to a drain (if this is not possible then their water outlet needs to be piped several meters away from the building) as the resulting wet area is highly conducive to termites.

Water tanks should not leak and the overflow should be adequately connected to storm water. A plumber should be engaged if the water tank overflow is not connected to storm water.

#### Was the overflow sufficiently drained

No - Divert hot water overflow away from the building perimeter



**Was the Air Conditioner Sufficiently Drained**

No - Divert A/C overflow away from the building perimeter



## **4.2 Moisture Readings**

### **Was there any Excessive Moisture Readings**

At the time of the inspection moisture readings were high



Master bedroom

### **Please Note**

High moisture readings can be caused by any one of the following: Poor ventilation, ineffective drainage, leaking pipes, leaking roofs, defective flashing or by concealed termite activity. The areas of high moisture should be investigated by way of an invasive inspection. If high moisture was reported then you must have a building expert investigate the moisture and its cause and determine the full extent of damage and the estimated cost of repairs.

### **Equipment Of Moisture detection used**

If high moisture was reported then you must have a building expert investigate the moisture and its cause and determine the full extent of damage and the estimated cost of repairs.

Termatrac

### **4.3 Sub Floor Ventilation**

#### **Sub Floor Ventilation is Generally**

The ventilation isn't adequate in the subfloor. This needs to be improved by either clearing/exposing all air vents to enable sufficient airflow or potentially installing further vents in the external walls. This lack of good ventilation is a conducive condition for termites.



#### **4.5 Weep Holes and Sub Floor Vents**

**Were the vents clear**

Yes

#### **Please Note**

It is very important that soil, lawn, concrete paths or pavers do not cover the weep holes. Sometimes they have been covered during the rendering of the brick work. They should be clean and free flowing. Covering the weep holes in part or in whole may allow undetected termite entry.

#### **5. Ant Capping and Termite Shields**

**The Termite Shields Appear To Be**

The termite shields ( ant caps ) are inadequate



### **Please Note**

Termite shields (ant caps) should be in good order and condition so termite workings are exposed and visible. This helps stop termites gaining undetected entry. Joins in the shielding should have been soldered during the installation. Whenever it is observed that the joins in the shielding have not been soldered then the shielding must be reported as inadequate. It may be possible for a builder to repair the shielding. If not, a chemical treated zone may need to be installed to deter termites from gaining concealed access to the building. Missing, damaged or poor shields increase the risk of termite infestation. If considered inadequate a builder or other building expert should be consulted. Other physical shield systems are not visible to inspection and no comment is made on such systems.

## **6. Areas Found Conducive To Termite Infestation**

### **Conducive Areas Requiring Amendments**

Wall mounted air conditioner overflow requires diverting to drain. This provides conducive conditions for termite infestation. Engage plumber to rectify.

Down pipes not connected to storm water. This causes moisture and excess moisture is conducive to termite infestation. The degree of risk is high. You need to engage a plumber to rectify.

Leaking down pipe joins. This causes moisture and excess moisture is conducive to termite infestation. The degree of risk is moderate to high. You need to engage a plumber to rectify.

Timber fungal decay located around the home provides conducive conditions for termite infestation. The degree of risk is high. Have removed and replaced by a carpenter.

Gutter joins leaking. This causes moisture and excess moisture is conducive to termite infestation. The degree of risk is moderate to high. You need to engage a plumber to rectify.

Gutter leaking due to rust. This causes moisture and excess moisture is conducive to termite infestation. The degree of risk is moderate to high. You need to engage a plumber to rectify.

Hot water unit overflow not connected to drain. This provides conducive conditions for termite infestation. The degree of risk is moderate to high. Engage plumber to rectify.

There is no termite shields or ant capping on the stump footings. This makes it difficult to observe termite workings into the sub floor timber.

Poor drainage - There is water ponding against walls. This provides conducive conditions for termite infestation. The degree of risk is high. Engage plumber to rectify.

Surface water drainage: Surface water drainage needs assessing and rectifying by a qualified plumber. This excessive moisture can cause conducive conditions for termites. The degree of risk is moderate to high.

Timber debris in contact with ground in sub floor. This provides conducive and concealed conditions for termite infestation. The degree of risk is high. Remove.

Tree/leafy environment: The house is located in a suburb which is high risk due to the environmental surrounds. It is close to large gum trees and parkland. The degree of risk is moderate to high and therefore a termite management plan/treatment is strongly advised.

Rising damp detected. A qualified damp proof specialist should be engaged for advice and recommendations. Accurate diagnosis of the cause and extent of the damp problem is very important. Note: It is imperative that specialist advice be sought to obtain accurate diagnosis of the cause and extent of the damp problem and it is advised that you have assessed prior to purchasing the dwelling as can be quite costly if a damp proof course has to be reinstated.

Downpipe Base is cracked seek expert advice from a licensed plumber for immediate repair.

Downpipe Base is broken seek immediate advice from a licensed plumber for immediate repair.

Downpipe is rusted seek expert advice from a licensed plumber to repair immediately.

## **7. Environmental Conditions**

### **Are Trees Close to Home**

Trees are in close proximity to the dwelling and within the termite foraging area. These are a favorable influence for termite infestation and i recommend you liaise with the neighbours to have regularly checked and if in your site, organise regular inspections for termite infestation.



### **Other Informational**

Refer to important maintenance advice regarding ipm below.



# OVERALL ASSESSMENT

## 9. Overall Assessment of Property

### **Please Note**

Where or if there has been evidence of live termites or termite damage or termite workings (mudding) found in the building(s) then the risk of a further attack is extremely high. Where evidence of live termites or termite damage or termite workings was found in the grounds but not in the buildings then the risk to buildings must be reported as high to extremely high.

### **Degree of Risk of Termite Infestation is**

The overall degree of risk of timber pest infestation to this property appears to be high - See notes below.

The overall degree of risk of timber pest infestation is a subjective assessment by the inspector at the time of the inspection taking into account many factors which include but are in no way limited to location and proximity to bush land and trees, the presence of evidence of timber pest damage or activity close to the inspected structure or within the inspected structure, conducive conditions that raise the potential of timber pest attack such as timbers in contact with soil, inaccessible areas, slab on ground construction etc, or other factors that in the inspectors opinion, raise the risk of future timber pest attack. It should be noted that even if a risk factor is high, this is not meant to deter a purchaser from purchasing the property, it is just to make them aware that increased vigilance is warranted and any recommendations regarding reducing conducive conditions or frequency of inspections should be headed by any property owner. Often, by reducing or eliminating some of the conducive conditions, the risk factor may be lowered.

## 10. Subterranean Termite Treatment Recommendation

### **Treatment Recommendation**

A management program in accord with AS 3660-2000 to protect against subterranean termites is considered to be: ESSENTIAL

Termite prevention wasn't detected during inspection treatment is due now.

## 11. Future Inspections

### **Future Inspections**

Future inspections: As 3660.2-2000 Recommends that inspections be carried out at intervals no greater than annually and where timber pest "pressure" is greater, this interval should be shortened. Inspections will not stop timber pest infestations; however, the damage which may be caused will be reduced when the infestation is found at an early stage.

Due to the degree of risk of subterranean termite infestation noted above and all other findings of this report, we strongly recommend that a full inspection and written report in accord with as 4349.3 Or as 3660.2-2000

### **Recommended Inspection Intervals**

3 months or on settlement.

## **12. General Remarks**

### **Please Read**

Please read: A more thorough invasive inspection is available. Where any current visible evidence of timber pest activity is found it is strongly recommended that a more invasive inspection is performed. Trees on the property up to a height of 2m have been visually inspected, where possible and practicable, for evidence of termite activity. It is very difficult, and generally impossible to locate termite nests since they are underground and evidence in trees is usually well concealed. We therefore strongly recommend that you arrange to have trees test drilled for evidence of termite nests.

Important maintenance advice regarding integrated pest management for protecting against timber pests  
Any structure can be attacked by timber pests. Periodic maintenance should include measures to minimize possibilities of infestation in and around a property. Factors which may lead to infestation from timber pests include situations where the edge of the concrete slab is covered by soil or garden debris, filled areas, areas with less than 400mm clearance, foam insulation at foundations, earth/wood contact, damp areas, leaking pipes, etc.; Form-work timbers, scrap timber, tree stumps, mulch, tree branches touching the structure, wood rot, etc. Gardens, pathways or turf abutting or concealing the edge of a concrete slab will allow for concealed entry by timber pests. Any timber in contact with soil such as form-work, scrap timbers or stumps must be removed from under and around the buildings and any leaks repaired. You should endeavor to ensure such conditions do not occur around your property.

It is strongly recommended that a full inspection to as 4349.3 Or as 3660.2-2000 Be carried out at least once every 12 months. Regular inspections do not stop timber pest attack, but are designed to limit the amount of damage that may occur by detecting problems early.

We further advise that you engage a professional pest control firm to provide a termite management program in accord with as 3660 to minimize the risk of termite attack. There is no way of preventing termite attack. Even as 3660 advises that "the provision of a complete termite barrier will impede and discourage termite entry into a building. It cannot prevent termite attack. Termites can still bridge or breach barriers but they can be detected more readily during routine inspections."

Disclaimer of liability:- No liability shall be accepted on account of failure of the report to notify any termite activity and/or damage present at or prior to the date of the report in any areas(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the licensed inspector (including but not limited to any area(s) or section(s) so specified by the report).

Disclaimer of liability to third parties: - This report is made solely for the use and benefit of the client named on the front of this report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the report wholly or in part. Any third party acting or relying on this report, in whole or in part, does so at their own risk.

Before you decide to purchase this property you should read and understand the following important information. It will help explain what is involved in a timber pest inspection, the difficulties faced by a timber pest inspector and why it is not possible to guarantee that a property is free of timber pests. It also details important information about what you can do to help protect your property from timber pests. This information forms an integral part of the report.

## **13. Reasonable Access**

### **Access to Inspect**

The Building and the site including fencing that is up to 30 meters from the building and within the boundaries of the site. Where present and accessible, the Inspection shall include.

- (a) The interior of the building.
- (b) The roof space.
- (c) The exterior of the building
- (d) The sub-floor space
- (e) The roof exterior
- (f ) The property within 30 m of the building subject to inspection.

### **Visual Inspection Only**

This is a visual inspection only limited to those areas and sections of the property fully accessible and visible to the inspector on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/ sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, behind stored goods in cupboards and other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. Visible timbers cannot be destructively probed or hit without the written permission of the property owner.

### **Very Important note to the purchaser.**

In the event that areas where access is restricted or not accessed structural defects, termite damage or activity may be present but not seen. Access should be provided and a follow up or re-Inspection should take place. This Inspection will be provided for you at no cost. Please consult with the vendor and request full access to restricted areas. This should be done prior to a decision to purchase.

Access to inspect:

Only areas to which reasonable access is available were inspected. The Australian standard 4349.3 Defines reasonable access as "areas where safe, unobstructed access is provided and the minimum clearances specified in the table below are available or, where these clearances are not available, areas within the consultant's unobstructed line of sight and within arm's length. Reasonable access does not include removing screws and bolts to access covers." Reasonable access does not include the use of destructive or invasive inspection methods. Nor does reasonable access include cutting or making access traps, or moving heavy furniture or stored goods.

A more thorough invasive inspection is available. Where any current visible evidence of timber pest activity is found it is strongly recommended that a more invasive inspection is performed. Trees on the property up to a height of 2m have been visually inspected, where possible and practicable, for evidence of termite activity. It is very difficult, and generally impossible to locate termite nests since they are underground and evidence in trees is usually well concealed. We therefore strongly recommend that you arrange to have trees test drilled for evidence of termite nests.

Important maintenance advice regarding integrated pest management for protecting against timber pests.

Any structure can be attacked by timber pests. Periodic maintenance should include measures to minimize possibilities of infestation in and around a property. Factors which may lead to infestation from timber pests include situations where the edge of the concrete slab is covered by soil or garden debris, filled areas, areas with less than 400mm clearance, foam insulation at foundations, earth/wood contact, damp areas, leaking pipes, etc.; Form-work timbers, scrap timber, tree stumps, mulch, tree branches touching the structure, wood rot, etc. Gardens, pathways or turf abutting or concealing the edge of a concrete slab will allow for concealed entry by timber pests. Any timber in contact with soil such as form-work, scrap timbers or stumps must be removed from under and around the buildings and any leaks repaired. You should endeavor to ensure such conditions do not occur around your property.

It is strongly recommended that a full inspection to as 4349.3 Or as 3660.2-2000 Be carried out at least once every 12 months. Regular inspections do not stop timber pest attack, but are designed to limit the amount of damage that may occur by detecting problems early.

We further advise that you engage a professional pest control firm to provide a termite management program in accord with as 3660 to minimize the risk of termite attack. There is no way of preventing termite attack. Even as 3660 advises that "the provision of a complete termite barrier will impede and discourage termite entry into a building. It cannot prevent termite attack. Termites can still bridge or breach barriers but they can be detected more readily during routine inspections."

**Disclaimer of liability:** No liability shall be accepted on account of failure of the report to notify any termite activity and/or damage present at or prior to the date of the report in any areas(s) or section(s) of the subject property physically inaccessible for inspection, or to which access for inspection is denied by or to the licensed inspector (including but not limited to any area(s) or section(s) so specified by the report).

**Disclaimer of liability to third parties:** This report is made solely for the use and benefit of the client named on the front of this report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the report wholly or in part. Any third party acting or relying on this report, in whole or in part, does so at their own risk.

Before you decide to purchase this property you should read and understand the following important information. It will help explain what is involved in a timber pest inspection, the difficulties faced by a timber pest inspector and why it is not possible to guarantee that a property is free of timber pests. It also details important information about what you can do to help protect your property from timber pests. This information forms an integral part of the report.

Area access hole into roof space - 450 X 400mm access hole required

Crawl space height in actual roof space - 600 X 600mm crawl space required

Height from floor into roof space - Accessible from 2.1M step ladder or 3.6M ladder placed against a wall.

Subfloor access hole - 500 X 400mm access hole required

Timber sub floor clearance required - 400Mm to bearer, joist or other obstruction

Concrete floor - 500Mm roof exterior accessible from a 3.6M ladder

Roof exterior - Accessible with a 3.6 Meter ladder

A more invasive physical inspection is available and recommended.

As detailed above, there are many limitations to this visual inspection only. With the permission of the owner of the premises we will perform a more invasive physical inspection that involves moving or lifting: Insulation, stored items, furniture or foliage during the inspection. We will physically touch, tap, test and when necessary force/ gouge suspected accessible timbers. We will gain access to areas, where physically possible and considered practical and necessary, by way of cutting traps and access holes. This style of report is available by ordering with several days' notice. Inspection time for this style of report will be greater than for a visual inspection. It involves disruption in the case of an occupied property, and some permanent marking is likely. You must arrange for the written permission of the owner who must acknowledge all the above information and confirm that our firm will not be held liable for any damage caused to the property. Price is available on request.

### **Visual Inspection Only**

This is a visual inspection only limited to those areas and sections of the property fully accessible and visible to the inspector on the date of inspection. The inspection did not include breaking apart, dismantling, removing or moving objects including, but not limited to, foliage, mouldings, roof insulation/ sisalation, floor or wall coverings, sidings, ceilings, floors, furnishings, appliances or personal possessions. The inspector cannot see inside walls, between floors, inside skillion roofing, behind stored goods in cupboards and other areas that are concealed or obstructed. The inspector did not dig, gouge, force or perform any other invasive procedures. Visible timbers cannot be destructively probed or hit without the written permission of the property owner.

### **Very Important note to the purchaser.**

In the event that areas where access is restricted or not accessed structural defects, termite damage or activity may be present but not seen. Access should be provided and a follow up or re-Inspection should take place. This Inspection will be provided for you for a fee. Please consult with the vendor and request full access to restricted areas. This should be done prior to a decision to purchase.

## **14. Maintenance Advice**

### **Please Read**

Important maintenance advice regarding integrated pest management (ipm) for protecting against timber pests:

No property is safe from termites!

Termites are the cause of the greatest economic losses of timber in service in australia.

Independent data compiled by state forests shows 1 in every 5 homes is attacked by termites at some stage in its life. Australia's subterranean termite species (white ants) are the most destructive timber pests in the world. In fact it can take "as little as 3 months for a termite colony to severely damage almost all the timber in a home".

### **How termites attack your home**

The most destructive species live in large underground nests containing several million timber destroying insects. The problem arises when a nest matures near your home. Your home provides natural shelter and a food source for the termites. The gallery system of a single colony may exploit food sources over as much as one hectare, with individual galleries extending up to 50 meters to enter your home, where there is a smörgåsbord of timber to feast upon. Even concrete slabs do not act as a barrier; they can penetrate through cracks in the slab to gain access to your home. They even build mud tubes to gain access to above ground timbers. In rare cases termites may create their nest in the cavity wall of the property without making ground contact. In these cases it may be impossible to determine their presence until extensive timber damage occurs.

### **Termite damage**

Once in contact with the timber they excavate it often leaving only a thin veneer on the outside. If left undiscovered the economic species can cause many thousands of dollars damage and cost two to five thousand dollars (or more) to treat.

### Subterranean termite ecology

These termites are social insects usually living in underground nests. Nests may be in trees or in rare instances they may be in above ground areas within the property. They tunnel underground to enter the building and then remain hidden within the timber making it very difficult to locate them. Where timbers are concealed, as in most modern homes, it makes it even more difficult to locate their presence. Especially if gardens have been built up around the home and termite barriers are either not in place or poorly maintained. Termites form nests in all sorts of locations and they are usually not visible. There may be more than one nest on a property. The diet of termites in the natural environment is the various hardwood and softwood species growing throughout Australia. These same timbers are used in buildings. Worker termites move out from their underground nest into surrounding areas where they obtain food and return to nurture the other casts of termites within the nest. Termites are extremely sensitive to temperature, humidity and light and hence cannot move over ground like most insects. They travel in mud encrusted tunnels to the source of food. Detection of termites is usually by locating these mud tunnels rising from the ground into the affected structure. This takes an expert eye. Termite barriers protect a building by forcing termites to show themselves. Termites can build mud tunnels around termite barriers to reach the timber above. The presence of termite tracks or leads does not necessarily mean that termites have entered the timber though. A clear view of walls and piers and easy access to the sub-floor means that detection should be fairly easy. However many styles of construction do not lend themselves to ready detection of termites. The design of some properties is such that they make the detection by a pest inspector difficult, if not impossible. The tapping and probing of walls and internal timbers is an adjunct or additional means of detection of termites but is not as reliable as locating tracks. The use of a moisture meter is a useful aid for determining the presence of termites concealed behind thin wall panels, but it only detects high levels of activity. Older damage that has dried out will not be recorded. It may also provide false readings. Termite tracks may be present in the ceiling space however some roofs of a low pitch and with the presence of insulation, air conditioning ductwork and hot water services may prevent a full inspection of the timbers in these areas. Therefore since foolproof and absolute certain detection is not possible the use of protective barriers and regular inspections is a necessary step in protecting timbers from termite attack.

### Borers of seasoned timbers

Borers are the larvae of various species of beetles. The adult beetles lay their eggs within the timber. The eggs hatch out into larvae (grubs) which bore through the timber and can cause significant structural damage. The larvae may reside totally concealed within the timber for a period of several years before passing into a dormant pupae stage. Within the pupae case they metamorphose (change) into the adult beetle which cuts a hole in the outer surface of the timber to emerge, mate and lay further eggs to continue the cycle. It is only through the presence of these emergence holes, and the frass formed when the beetles cut the exit holes that their presence can be detected. Where floors are covered by carpets, tiling, or other floor coverings and where no access to the under floor area is available it is not possible to determine whether borers are present or not. This is particularly the case with the upper floors of a dwelling. Borers of 'green' unseasoned timber may also be present. However these species will naturally die out as the timbers dry out in service. Whilst some emergence holes may occur in a new property it would be unusual for such a borer to cause structural damage, though the exit holes may be unsightly.

### Anobium borer (furniture beetle) and Queensland pine borer

These beetles are responsible for instances of flooring collapse, often triggered by a heavy object being placed on the floor (or a person stepping on the affected area!) Pine timbers are favored by this beetle and, while the sapwood is preferred, the heartwood is also sometimes attacked. Attack by this beetle is usually observed in timbers that have been in service for 10-20 years or more and mostly involves flooring and timber wall paneling. The frass from the flight holes (faeces and chewed wood) is fine and gritty. Wood attacked by these borers is often honeycombed.

### Lyctus borer (powder post beetle)

These borers only attack the sapwood of certain susceptible species of hardwood timber. Since it is a requirement that structural timbers contain no more than 25% lyctus susceptible sapwood these borers are not normally associated with structural damage. Replacement of affected timbers is not recommended and treatment is not approved. Where decorative timbers are affected the emergence holes may be considered unsightly in which case timber replacement is the only option. Powder post beetles mostly attack during the first 6-12 months of service life of timber. As only the sapwood is destroyed, larger dimensional timbers (such as rafters, bearers and joists) in a house are seldom weakened significantly to cause collapse. In small dimensional timbers (such as tiling and ceiling battens) the sapwood may be extensive, and its destruction may result in collapse. Replacement of these timbers is the only option available.

#### Timber decay fungi

The fruiting bodies of wood decay fungi vary in size, shape and colour. The type of fungi encountered by pest controllers usually reside in poorly ventilated sub-floors, below wet areas of the home, exterior timbers and in areas that retain water in the soil. The durability and type of timbers are factors along with the temperature and environment. Destruction of affected timbers varies with the symptoms involved. Removal of the moisture source usually alleviates the problem. Fungal decay is attractive to termites and if the problem is not rectified it may well lead to future termite attack.

**The Inspection and Report was carried out by: Raymond French**

**State License Number: Loo 3022 HS111 Reg.2223092766VIC**

**Contact the Inspector on: 0400 886 170**

**For and on Behalf of: Home Inspections For A Better Peace Of Mind.**

